

A96/Reiket Lane, Elgin (NJ 235 624) - T junction to Roundabout - changed Summer 2006

1996-2005 Before
two recorded injury accidents

Accident: 200203254

Date	23/09/2002
Time	15:00:00
Day of week	Monday
Severity of accident	Slight
Location Easting	323585
Location Northing	862451
Speed limit	40mph
Junction detail	T junction or staggered junction
Light conditions	Daylight, street lights present
Weather	Fine, no high winds
Road surface condition	Dry
Cause 1	Turning right at a road junction without due care
Description of Accident	
Location Description	A96 Lhanbryde to Elgin Road at its T junction with Reiket Lane, Elgin, Moray.

2007-2015
five recorded injury accidents

Accident: 200701519

Date	04/05/2007
Time	18:30:00
Day of week	Friday
Severity of accident	Slight
Location Easting	323640
Location Northing	862430
Speed limit	40mph
Junction detail	Roundabout
Light conditions	Daylight, street lights present
Weather	Fine, no high winds
Road surface condition	Dry
Description of Accident	
Location Description	A96, East Road, Elgin at its junction with Reiket Lane.
Accident reference	701519
Collision Factor 1	Following too close
CF1 Veh/Cas/Uninj	Vehicle
CF1 Veh/Cas/Uninj RefNum	1

Vehicle: 1

Vehicle type	Car
Vehicle movement from	S
Vehicle movement to	E
Manoeuvres	Turning right

Vehicle: 2

Vehicle type	Minibus (8-16 pass)
Vehicle movement from	E
Vehicle movement to	W
Manoeuvres	Going ahead - other

Casualty: 1

Vehicle reference number	2
Class of casualty	Vehicle/pillion passenger
Severity of casualty	Slight

Accident: 961671

Date	22/04/1996
------	------------

Confidence CF1	Very Likely
Collision Factor 2	UNKNOWN
CF2 Veh/Cas/Uninj	UNKNOWN
CF2 Veh/Cas/Uninj RefNum	

Vehicle: 1

Vehicle type	Car
Vehicle movement from	SE
Vehicle movement to	NW
Manoeuvres	Going ahead - other

Vehicle: 2

Vehicle type	Car
Vehicle movement from	SE
Vehicle movement to	NW
Manoeuvres	Going ahead - other

Vehicle: 3

Vehicle type	Car
--------------	-----

Time	17:00:00
Day of week	Monday
Severity of accident	Slight
Junction detail	T junction or staggered junction
Light conditions	Daylight, street lights present
Weather	Fine, no high winds
Location Description	A96 ELGIN/LHANBRYDE ROAD AT JUNCTION WITH REIKET LANE ELGIN

Vehicle: 1

Vehicle type	Car
Vehicle movement from	S
Vehicle movement to	E
Manoeuvres	Turning right

Vehicle: 2

Vehicle type	Car
Vehicle movement from	E
Vehicle movement to	W
Manoeuvres	Going ahead - other

Vehicle movement from	SE
Vehicle movement to	NW
Manoeuvres	Going ahead - other

Casualty: 1

Vehicle reference number	1
Class of casualty	Driver/rider
Severity of casualty	Slight
Sex of casualty	Female

Accident: 200805280

Date	03/09/2008
Time	08:20:00
Day of week	Wednesday
Severity of accident	Slight
Location Easting	323510
Location Northing	862480
Speed limit	40mph
Junction detail	Not at or within 20m of junction
Light conditions	Daylight, no street lighting
Weather	Fine, no high winds
Road surface condition	Dry

Casualty: 1

Vehicle reference number	1
Class of casualty	Driver/rider
Severity of casualty	Slight

Casualty: 2

Vehicle reference number	2
Class of casualty	Driver/rider
Severity of casualty	Slight

Description of Accident	At 0820 hours, on 3 September 2008, at the bus stop on East Road, near to its junction with Reiket Lane, Elgin, some children were waiting for the bus. As the bus arrived at the stop, the child was struck on the side of the head by it causing him to fall to the ground.
Location Description	A96 Elgin to Fochabers road at the bus stop on East Road near to its junction with Reiket Lane, Elgin.
Collision Factor 1	Failed to look properly
CF1 Veh/Cas/Uninj	Vehicle
CF1 Veh/Cas/Uninj RefNum	1
Confidence CF1	Very Likely
Collision Factor 2	Passing too close to cyclist, horse rider or pedestrian
CF2 Veh/Cas/Uninj	Vehicle
CF2 Veh/Cas/Uninj RefNum	1

Vehicle: 1

Vehicle type	Bus or coach (17 or more passenger seats)
Vehicle movement from	NW
Vehicle movement to	SE

Casualty: 1

Vehicle reference number	1
Class of casualty	Pedestrian
Severity of casualty	Slight
Sex of casualty	Male

Accident: 201200373

Date	20/01/2012
Time	14:45:00
Day of week	Friday
Severity of accident	Slight
Location Easting	323600
Location Northing	862470
Speed limit	40mph
Junction detail	Roundabout
Light conditions	Daylight, street lights present
Weather	Unknown
Road surface condition	Dry
Description of Accident	V1 was travelling east on the A96 and was turning right on to Reiket Lane, Elgin on the inside lane of the roundabout there. V2 was also travelling east and was going straight ahead at the roundabout. V2 came up the nearside of V1 on the roundabout and cut across its lane causing its offside to collide with the front nearside of V1.

Location Description	A96 East Road, Elgin at its roundabout junction with Reiket Lane.
Collision Factor 1	Poor turn or manoeuvre
CF1 Veh/Cas/Uninj	Vehicle
CF1 Veh/Cas/Uninj RefNum	2
Confidence CF1	Very Likely
Collision Factor 2	UNKNOWN
CF2 Veh/Cas/Uninj	UNKNOWN
CF2 Veh/Cas/Uninj RefNum	

Vehicle: 1

Vehicle type	Car
Vehicle movement from	W
Vehicle movement to	S
Manoeuvres	Turning right

Vehicle: 2

Vehicle type	Bus or coach (17 or more passenger seats)
Vehicle movement from	W
Vehicle movement to	E
Manoeuvres	Going ahead - other

Casualty: 1

Vehicle reference number	1
Class of casualty	Driver/rider
Severity of casualty	Slight
Sex of casualty	Female

Casualty: 2

Vehicle reference number	1
Class of casualty	Vehicle/pillion passenger
Severity of casualty	Slight
Sex of casualty	Female

Casualty: 3

Vehicle reference number	1
Class of casualty	Vehicle/pillion passenger
Severity of casualty	Slight
Sex of casualty	Male

Accident: 201301839

Date	10/05/2013
Time	13:05:00
Day of week	Friday
Severity of accident	Serious
Location Easting	323675
Location Northing	862418
Speed limit	40mph
Junction detail	Not at or within 20m of junction
Light conditions	Daylight, street lights present
Weather	Fine, no high winds
Road surface condition	Dry
Description of Accident	About 1305 hours on Friday 10 May 2013 vehicle 2 was travelling west along the A96 in a queue of traffic. The driver was slowing down and nearly stopped waiting for traffic to clear the roundabout in front of him when the driver looked in his rear view mirror and saw a motorcycle, vehicle 1 travelling towards his car. Vehicle 1 collided with the rear of vehicle 2 and the rider fell off.
Location Description	A96, approximately 50 metres east of KFC roundabout, Elgin
Collision Factor 1	Careless/Reckless/In a hurry
CF1 Veh/Cas/Uninj	Vehicle
CF1 Veh/Cas/Uninj RefNum	1
Confidence CF1	Very Likely
Collision Factor 2	Failed to judge vehicle's path or speed
CF2 Veh/Cas/Uninj	Vehicle
CF2 Veh/Cas/Uninj RefNum	1
Confidence CF2	Possible

Vehicle: 1

Vehicle type	Motorcycle over 500cc
Vehicle movement from	E
Vehicle movement to	W
Manoeuvres	Going ahead - other

Vehicle: 2

Vehicle type	Car
Vehicle movement from	E
Vehicle movement to	W
Manoeuvres	Waiting to go ahead, held up

Casualty: 1

Vehicle reference number	1
Class of casualty	Driver/rider
Severity of casualty	Serious
Sex of casualty	Male

Accident: 201400248

Date	24/02/2014
Time	16:30:00
Day of week	Monday
Severity of accident	Slight
Location Easting	323621
Location Northing	862434
Speed limit	40mph
Junction detail	Roundabout
Light conditions	Daylight, street lights present
Weather	Fine, no high winds
Road surface condition	Dry
Description of Accident	About 1630 hours on Monday 24 February 2014 vehicle 2 was travelling along the A96 and was approaching the roundabout with Reiket Lane. At this time Vehicle 1 was following vehicle 2. Vehicle 2 slowed down and stopped due to a vehicle travelling round the roundabout and vehicle 1 collided with the rear of vehicle 2.
Location Description	A96, Elgin at the roundabout with Reiket Lane, Elgin, Moray
Collision Factor 1	Deposit on road (eg. oil, mud, chippings)
CF1 Veh/Cas/Uninj	Vehicle
CF1 Veh/Cas/Uninj RefNum	1
Confidence CF1	Very Likely
Collision Factor 2	Failed to look properly
CF2 Veh/Cas/Uninj	Vehicle

CF2 Veh/Cas/Uninj RefNum	1
Confidence CF2	Possible

Vehicle: 1

Vehicle type	Car
Vehicle movement from	E
Vehicle movement to	W
Manoeuvres	Going ahead - other

Vehicle: 2

Vehicle type	Car
Vehicle movement from	E
Vehicle movement to	W
Manoeuvres	Waiting to go ahead, held up

Casualty: 1

Vehicle reference number	2
Class of casualty	Driver/rider
Severity of casualty	Slight
Sex of casualty	Male

A941 Main Street/Birnie Road/Thornhill Road (NJ 221 611)- Staggered crossroads to roundabo

1995 -2004

1 injury accident

Accident: 200002389

Date	07/07/2000
Time	07:30:00
Day of week	Friday
Severity of accident	Slight
Location Easting	322183
Location Northing	861193
Speed limit	30mph
Junction detail	T junction or staggered junction
Light conditions	Daylight, street lights present
Weather	Fine, no high winds
Road surface condition	Wet or damp
Cause 1	Inattentive or attention distracted
Description of Accident	
Location Description	A941 Elgin to Rothes road at its junction with Thornhill Road, Elgin

Vehicle: 1

Vehicle type	Car
Vehicle movement from	S
Vehicle movement to	N
Manoeuvres	Going ahead - other

Casualty: 1

Vehicle reference number	1
Class of casualty	Driver/rider
Severity of casualty	Slight

ut - October 2005

2006 - 2015

2 injury accidents

Accident: 200703979

Date	27/11/2007
Time	06:40:00
Day of week	Tuesday
Severity of accident	Slight
Location Easting	322180
Location Northing	861200
Speed limit	30mph
Junction detail	Roundabout
Light conditions	Darkness, street lights, lit
Weather	Fine, no high winds
Road surface condition	Wet or damp
Description of Accident	V1 was being ridden eastwards on Birnie Road, Elgin and on reaching the roundabout junction with the A941 Elgin to Rothes road he started to negotiate the roundabout. V2 was being driven SOUTHWARDS on the A941 Elgin to Rothes road and as he reached the roundabout junction he drove onto it, in front of V1 and V1 collided with the offside of V2 and the rider fell off onto the road.
Location Description	The A941 Elgin to Rothes road at roundabout with Thornhill Road, Elgin.
Collision Factor 1	Failed to look properly
CF1 Veh/Cas/Uninj	Vehicle
CF1 Veh/Cas/Uninj RefNum	2
Confidence CF1	Very Likely
Collision Factor 2	UNKNOWN
CF2 Veh/Cas/Uninj	UNKNOWN
CF2 Veh/Cas/Uninj RefNum	

Vehicle: 1

Vehicle type	Motorcycle over 50cc and up to 125cc
Vehicle movement from	W
Vehicle movement to	E
Manoeuvres	Going ahead - other

Vehicle: 2

Vehicle type	Car
Vehicle movement from	N
Vehicle movement to	S
Manoeuvres	Going ahead - other

Casualty: 1

Vehicle reference number	1
Class of casualty	Driver/rider
Severity of casualty	Slight
Sex of casualty	Male

Accident: 200801629

Date	18/04/2008
Time	14:40:00
Day of week	Friday
Severity of accident	Serious
Location Easting	322240
Location Northing	861210
Speed limit	30mph
Junction detail	Other junction
Light conditions	Daylight, street lights present
Weather	Fine, no high winds
Road surface condition	Dry

Description of Accident	V1 came from the direction of Birnie Road , round the roundabout and onto Thornhill Road heading east V2 had just exited Murray Street and was moving east along Thornhill slowly speeding up. At this time V1 appeared to fail to anticipate the slower moving speed of the vehicle in front and collided with the rear of V2 throwing the rider onto the roof before he came to rest on the road behind the motor car.
Location Description	Thornhill Road Elgin just east of its junction with Murray Street, Elgin.
Collision Factor 1	Failed to look properly
CF1 Veh/Cas/Uninj	Vehicle
CF1 Veh/Cas/Uninj RefNum	1
Confidence CF1	Very Likely
Collision Factor 2	Failed to judge other person's path or speed
CF2 Veh/Cas/Uninj	Vehicle
CF2 Veh/Cas/Uninj RefNum	1

Vehicle: 1

Vehicle type	Motorcycle over 50cc and up to 125cc
Vehicle movement from	W
Vehicle movement to	E
Manoeuvres	Going ahead - other

Vehicle: 2

Vehicle type	Car
Vehicle movement from	W
Vehicle movement to	E
Manoeuvres	Going ahead - other

Casualty: 1

Vehicle reference number	1
Class of casualty	Driver/rider
Severity of casualty	Serious
Sex of casualty	Male

B9011/B9089 Main Street/Findhorn Road, Kinloss (NJ 063 616) - T junction to signals - chang
 There were cycle lanes at this junction on the main through route both before and after the s

1994-2003 Before
 ONE recorded injury accidents

Accident: 200300281

Date	22/01/2003
Time	07:15:00
Day of week	Wednesday
Severity of accident	Slight
Location Easting	306335
Location Northing	861622
Speed limit	30mph
Junction detail	T junction or staggered junction
Light conditions	Darkness, street lights, lit
Weather	Rain/hail, no high winds
Road surface condition	Wet or damp
Cause 1	Inadequate lights where not defective
Description of Accident	
Location Description	B9011 Findhorn to Kinloss Road at its junction with the B9089 Forres to Burghead Road, Moray

Vehicle: 1

Vehicle type	Car
Vehicle movement from	N
Vehicle movement to	E
Manoeuvres	Turning left

Vehicle: 2

Vehicle type	Pedal cycle
Vehicle movement from	W
Vehicle movement to	E
Manoeuvres	Going ahead - other

Casualty: 1

Vehicle reference number	2
Class of casualty	Driver/rider
Severity of casualty	Slight

ed 20/4/2004
signals were installed

2005-15 after
2 recorded injury accidents

Accident: 200500078

Date	02/01/2005
Time	02:20:00
Day of week	Sunday
Severity of accident	Slight
Location Easting	306324
Location Northing	861624
Speed limit	30mph
Junction detail	Not at or within 20m of junction
Light conditions	Darkness, street lights, lit
Weather	Fine, no high winds
Road surface condition	Frost or ice
Description of Accident	
Location Description	B9011 Forres to Kinloss Road, near its junction with B9011 Kinloss to Findhorn Road

Vehicle: 1

Vehicle type	Car
Vehicle movement from	S
Vehicle movement to	NE
Manoeuvres	Going ahead - RH bend

Casualty: 1

Vehicle reference number	1
Class of casualty	Driver/rider
Severity of casualty	Slight
Sex of casualty	Male

Casualty: 2

Vehicle reference number	1
Class of casualty	Vehicle/pillion passenger
Severity of casualty	Slight
Sex of casualty	Male

Accident: 200502313

Date	12/07/2005
Time	07:55:00
Day of week	Tuesday
Severity of accident	Slight
Location Easting	306366
Location Northing	861626
Speed limit	30mph
Junction detail	T/staggered junction
Light conditions	Daylight, street lights present
Weather	Fine, no high winds
Road surface condition	Dry
Description of Accident	
Location Description	B9089 Kinloss to Burghead road, at it's junction with the Spar car park entrance.
Accident reference	502313
Collision Factor 1	Failed to look properly
CF1 Veh/Cas/Uninj	Vehicle
CF1 Veh/Cas/Uninj RefNum	1
Confidence CF1	Very Likely
Collision Factor 2	UNKNOWN
CF2 Veh/Cas/Uninj	UNKNOWN
CF2 Veh/Cas/Uninj RefNum	

Vehicle: 1

Vehicle type	Goods vehicle under 3.5 tonnes
Vehicle movement from	E
Vehicle movement to	N
Manoeuvres	Turning right

Vehicle: 2

Vehicle type	Pedal cycle
--------------	-------------

Vehicle movement from	W
Vehicle movement to	E
Manoeuvres	Going ahead - other
Towing and articulation	No tow or articulation
Vehicle location - Restricted	Cycle lane (on main carriageway)

Casualty: 1

Vehicle reference number	2
Class of casualty	Driver/rider
Severity of casualty	Slight
Sex of casualty	Male