

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 214596 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/03/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 213720 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/02/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 213319 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/01/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 212139 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/12/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 211360 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/11/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 210511 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/10/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 209655 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/09/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 209217 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/08/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 207778 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 30/06/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 207581 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 29/07/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	2 New bushes fitted 7/25
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 206909 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/06/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	2 New bushes required
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 205649 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/05/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 205032 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/04/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 204153 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/03/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 203347 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/02/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 202419 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/01/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 201646 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/12/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

Batch: 200827 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/11/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 189948 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/10/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 189061 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/09/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 188213 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/08/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 187368 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/07/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 186527 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/06/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 185628 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 30/04/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 185139 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/04/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 184359 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/03/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 183473 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/02/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 182758 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/01/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 181599 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/12/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 181360 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/11/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 180588 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 12/10/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bushes and shackles replaced.08/23.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 179436 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/09/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 178470 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 31/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 177903 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 177137 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 176755 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 175729 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 172114 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 163049 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 159400 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 09/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 157143 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/12/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 151722 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 31/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 148617 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 04/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 145595 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/09/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 143572 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 142801 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/07/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 141985 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/06/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 141437 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/05/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 140843 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 139569 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 08/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 139206 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 138622 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 137369 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 18/11/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 136411 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 26/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 135653 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 27/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 135072 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 31/08/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 134127 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 27/07/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 133565 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 23/06/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 132812 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 18/05/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced. Bushes will need to be replaced on chain connection.18/05/21.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 132037 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 16/03/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19. replaced.
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 131295 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 17/02/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 130536 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 20/01/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 129780 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 16/12/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 129486 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 20/11/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 128261 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 14/07/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 127350 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 10/06/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 126603 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 12/05/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 125863 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/03/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 125108 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/02/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 124547 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 07/01/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 123802 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/12/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 123131 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 13/11/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 122308 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 01/10/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)
Route: Playground Inspection (P011)
Inspected: 01/01/2018 to 23/03/2026
Site: Well Road - Buckie (BUCKWELROA)

Location Contains: hurricane
Report Type: Assessment

Site: Well Road - Buckie (BUCKWELROA)

Area: Buckie

Plot Number: 4.01

Feature Id - Location: Wicksteed Hurricane Swing

Feature Type: Play Equipment Item

Contract Area: Grounds Maintenance

Batch: 121613 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/09/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 120756 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 06/08/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Bolt missing from seat base.6/8/19
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 120230 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 03/07/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 119345 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/06/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 118353 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 29/04/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 117803 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 02/04/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Batch: 117021 - Inspection Batch

Route: Playground Inspection

Officer: Playground Fitter

Date: 05/03/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

Officer: Playground Fitter (PLAY)**Route:** Playground Inspection (P011)**Inspected:** 01/01/2018 to 23/03/2026**Site:** Well Road - Buckie (BUCKWELROA)**Location Contains:** hurricane**Report Type:** Assessment**Site:** Well Road - Buckie (BUCKWELROA)**Area:** Buckie**Plot Number:** 4.01**Feature Id - Location:** Wicksteed Hurricane Swing**Feature Type:** Play Equipment Item**Contract Area:** Grounds Maintenance**Batch:** 116244 - Inspection Batch**Route:** Playground Inspection**Officer:** Playground Fitter**Date:** 29/01/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	