

**PROJECT WORKS**

Project	Year	MC Project Ref	Survey Company	Report Ref	ACM noted in report	Removals	Notes
Fire Safety Improvements - East End Primary School (Lot 4)	2012	68032	ESG	2012-4129001 (Management Report)	AIB canopy & gaskets	None	Contractor: Compass Building & Construction Services.
Nursery Extension	2014	61597/6	ESG	BS3239-4129001-04 (2013)	AIB canopy & gaskets	None	Contractor: Robertson Construction. (AEDAS Architects) CDM: Baker Mallet
Replacement of Folding Partitions	2014	68062	ESG	2014-4129001 (Management Report)	AIB canopy & gaskets	None	Contractor: David Stewart
Replace Heating Distribution Pipework, Replace Domestic Hot Water System and Electrical Power Upgrade - East End Primary East End Primary Make Do and Mend Phase 1&2	2013-2017	619116, 619119, 619115/B	ESG	BS3239-4129001-04 (2013) & ASL2310-200451- (2017)	AIB canopy & gaskets, roofing felt	AIB Canopy (adj area 1/7)- SEPA Note SA09871103.	Main Contractor: Morrison Construction. Removal contractor: Enviraz.
East End Primary - Refurbishment of Heritage Centre Phase 1/2/3	2016/17	619114	ESG	ASL2310-4129001-06 (2016)	Durasteel door, stair nosing, floor tiles & bitumen adhesive noted.	Stair nosings (area 2/12) & floor tiles (area 0/11c). SEPA note SA0986867	Contractor: Darroch & Allan. Asbestos Removal Contractor: NIS Scotland LTD. CDM Co-ordinators: Safehands.
East End Primary Flat Roof Replacement	2017	619110	ESG	Analysis Cert ASL2310-EEPS	Roofing felt	None	Contractor: Darroch & Allan. CDM Co-ordinators: Safehands.
<b>Other Projects: R&amp;D requested</b>							
(Kitchen refurb) -	2018		Environtec	J429713	No ACMs detected		
(External wall render/cladding) -	2021		Environtec	J684880	No ACMs detected		
Replacement Windows and Doors -	2020	619490	Environtec	J603889	No ACMs detected		

#NAME?