



## The Moray Council

Environmental Services - Direct Services  
Roads Maintenance

### USRN Inspection / Defect Records

USRN

263 / 52271

Street Name  
& Town

C2E From Birnie Road in Elgin to Glenlossie Road in Thomshill with branch via Dykeside to B9010,  
Elgin

Filter Used

(Defect Or Inspection Date is greater than or equal to 21 March 2016 00:00:00)

### Inspection History

#### Inspection Date Route Name

18/05/2016 Area W08 - 05 (May)

14/11/2016 Area W08 - 11 (Nov)

### Enquiries / Defects Recorded

Instruction Reference	Item Type / Detail	Defect Category	Instr. Time	Target Date	Comp. Date	Current Status	Location Description	Comments
R-51518	CARRIAGEWAY Pothole	Priority 2	16/05/16 09:48	12/06/16 16:00	10/06/16 16:00	Completed	20mtrs before B9010 junc 1 pothole on westbound side	E&C Pothole
R-51519	GULLY Blocked	Priority 2	16/05/16 09:50	12/06/16 16:00	19/05/16 16:00	Completed	At junction with B9010	Clear blocked newmill gully
R-51522	CARRIAGEWAY Pothole	Priority 2	16/05/16 10:27	12/06/16 16:00	09/06/16 16:00	Completed	100mtrs before The Level 1 pothole on southbound side	E&C Pothole
R-51523	VERGE Over-run damage	Priority 3	16/05/16 10:30	11/11/16 16:00	20/05/16 16:00	Completed	Opposite access road to The Level	Pull back verge to road edge approx 30mtrs long
R-51524	VERGE Over-run damage	Priority 3	16/05/16 10:32	11/11/16 16:00	20/05/16 16:00	Completed	From 30mtrs after Barholm on inside of righthand corner	Pull back verge to road edge 40mtrs long
R-51525	VERGE Over-run damage	Priority 3	16/05/16 10:34	11/11/16 16:00	20/05/16 16:00	Completed	30mtrs before U124e junction in west verge	Pull back verge to road edge 30mtrs long
R-51552	CARRIAGEWAY Carriageway Defects	Priority 3	16/05/16 12:37	12/11/16 16:00	29/07/16 16:00	Completed	400mtrs after pig feeding silos on southbound side of carriageway	Jetpatcher required to seal carriageway grazing/cracking 50mtrs long
R-51553	VERGE Fell Tree	Priority 2	16/05/16 12:42	13/06/16 16:00	14/06/16 16:00	Completed	At 30mph signs as you enter Thomshill in south verge	Cut Down tree that has split in the trunk and is obstructing 30mph sign, remove to depot for disposal
R-52094	VERGE Vegetation and Grass Cutting		07/06/16 09:32			No Further Action Required	The junction is on the Elgin to Dallas road, where you turn off to cross the Cloddach Bridge.	I would like to bring to your attention a very dangerous junction due to the grass not having been cut at it yet. This is already a fast section of road, and coming out of the junction is very dangerous due to the length of grass there. Thanks Heather cc
R-55870	DRAINAGE Blocked Offlets	Priority 3	14/11/16 10:00	12/05/17 16:00	02/12/16 16:00	Completed	From just after Elgin golf club access road to spur road to Birnie Church	Clear blocked off-lets
R-55871	DRAINAGE Blocked Offlets	Priority 3	14/11/16 10:04	12/05/17 16:00	30/11/16 16:00	Completed	Along full length of spur road to B9010 junction	Clear blocked off-lets
R-57185	VERGE Over-run damage	Priority 2	26/01/17 09:38	23/02/17 16:00	07/02/17 16:00	Works Complete (Awaiting Measure)	next to the new site layed out for driving range on southbound side of carriageway	Infill bottom ofverge over-run damage with asphalt plainings then with diggar pull back verge to road edge 30mtrs long. Approx 1/2 ton plainings required Working Man signs & Cones have been placed in over-run damage at present to mark site.



## The Moray Council

Environmental Services - Direct Services  
Roads Maintenance

### USRN Inspection / Defect Records

USRN

263 / 52271

Street Name  
& Town

C2E From Birnie Road in Elgin to Glenlossie Road in Thomshill with branch via Dykeside to B9010, Elgin

Filter Used

(Defect Or Inspection Date is greater than or equal to 21 March 2016 00:00:00)

