




<b>STREET</b>	C2E From Birnie Road in Elgin to Glenlossie Road in Thomshill with branch via Dykeside to B9010,		
<b>LOCATION</b>	Elgin On inside of lefthand corner just after spur road towards Birnie Church		
<b>FAULT COMMENTS</b>	Jetpatcher required to seal carriageway grazing/cracking approx 40mtrs long		
<b>ORDER COMMENTS</b>	Jetpatcher required to seal carriageway grazing/cracking approx 40mtrs long		
<b>ORDER DETAILS</b>	<i>Issue Date</i> 15/05/2017 09:41:00	<i>Completion Date</i> 20/06/2017 16:00:00	
	<i>Target Date</i> 10/11/2017 16:00:00	<i>Operative</i> [REDACTED]	
<b>GRID REF</b>	321531.00 , 859323.00		

ITEM CATEGORY	ITEM TYPE	ITEM DETAIL
ROADS MAINTENANCE	CARRIAGEWAY	Carriageway Defects



<b>TASK</b> Action	15/05/2017 09:41:16
<b>Actioned By</b>	[REDACTED]
<b>Action Result</b>	Approved For Works
<b>Comment</b>	
<b>Responsible Officer</b>	[REDACTED]

<b>TASK</b> Method of Payment	15/05/2017 09:41:27
<b>Method of Payment</b>	A/C Jetpatcher
<b>Contractor</b>	Roads Maintenance
<b>Notes</b>	