

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)

**Street Name & Town** Pluscarden Road,  
Elgin

**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
(Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Inspection History**

Inspection Date	Route Name
21/01/2016	Elgin South West - 01 (Jan) #
25/02/2016	Elgin South West - 02 (Feb) #
22/03/2016	Elgin South West - 03 (Mar) #
25/04/2016	Elgin South West - 04 (Apr) #
18/05/2016	Elgin South West - 05 (May) #
27/06/2016	Elgin South West - 06 (Jun) #
26/07/2016	Elgin South West - 07 (Jul) #
22/08/2016	Elgin South West - 08 (Aug) #
22/09/2016	Elgin South West - 09 (Sep) #
25/10/2016	Elgin South West - 10 (Oct) #
25/11/2016	Elgin South West - 11 (Nov) #
12/12/2016	Elgin South West - 12 (Dec) #
27/01/2017	Elgin South West - 01 (Jan) #
21/02/2017	Elgin South West - 02 (Feb) #
22/03/2017	Elgin South West - 03 (Mar) #
24/04/2017	Elgin South West - 04 (Apr) #
18/05/2017	Elgin South West - 05 (May) #
21/06/2017	Elgin South West - 06 (Jun) #
24/07/2017	Elgin South West - 07 (Jul) #
18/08/2017	Elgin South West - 08 (Aug) #
26/09/2017	Elgin South West - 09 (Sep) #
27/10/2017	Elgin South West - 10 (Oct) #
22/11/2017	Elgin South West - 11 (Nov) #
05/12/2017	Elgin South West - 12 (Dec) #
23/01/2018	Elgin South West - 01 (Jan) #
20/02/2018	Elgin South West - 02 (Feb) #
20/03/2018	Elgin South West - 03 (Mar) #
16/04/2018	Elgin South West - 04 (Apr) #
23/05/2018	Elgin South West - 05 (May) #
25/06/2018	Elgin South West - 06 (Jun) #
06/07/2018	Elgin South West - 07 (Jul) #
23/08/2018	Elgin South West - 08 (Aug) #
23/08/2018	Elgin South West - 08 (Aug) #
25/09/2018	Elgin South West - 09 (Sep) #
25/10/2018	Elgin South West - 10 (Oct) #
27/11/2018	Elgin South West - 11 (Nov)
13/12/2018	Elgin South West - 12 (Dec)
23/01/2019	Elgin South West - 01 (Jan)
28/02/2019	Elgin South West - 02 (Feb)

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Inspection History**

Inspection Date	Route Name
27/03/2019	Elgin South West - 03 (Mar)
24/04/2019	Elgin South West - 04 (Apr)
23/05/2019	Elgin South West - 05 (May)
27/06/2019	Elgin South West - 06 (Jun)
25/07/2019	Elgin South West - 07 (Jul)
26/08/2019	Elgin South West - 08 (Aug)
12/09/2019	Elgin South West - 09 (Sep)
21/10/2019	Elgin South West - 10 (Oct)
29/11/2019	Elgin South West - 11 (Nov)
12/12/2019	Elgin South West - 12 (Dec)
23/01/2020	Elgin South West - 01 (Jan)
26/02/2020	Elgin South West - 02 (Feb)
23/03/2020	Elgin South West - 03 (Mar)
13/04/2020	Elgin South West - 04 (Apr)
13/05/2020	Elgin South West - 05 (May)
16/06/2020	Elgin South West - 06 (Jun)
03/07/2020	Elgin South West - 07 (Jul)
24/08/2020	Elgin South West - 08 (Aug)
16/09/2020	Elgin South West - 09 (Sep)
27/10/2020	Elgin South West - 10 (Oct)
27/11/2020	Elgin South West - 11 (Nov)
21/12/2020	Elgin South West - 12 (Dec)
26/01/2021	Elgin South West - 01 (Jan)
17/02/2021	Elgin South West - 02 (Feb)
11/03/2021	Elgin South West - 03 (Mar)
15/04/2021	Elgin South West - 04 (Apr)
20/05/2021	Elgin South West - 05 (May)
23/06/2021	Elgin South West - 06 (Jun)
26/07/2021	Elgin South West - 07 (Jul)
30/08/2021	Elgin South West - 08 (Aug)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-47721	GULLY Blocked	07/01/16 10:01	Blocked gullys between Railway Bridge and River Bridge	Please unblock gullys	Noted					?

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-48559	CARRIAGEWAY Drainage Defects/Problems	02/02/16 14:15	█ Pluscarden Road	█	Closed	04/02/16 11:27	Priority 2	02/03/16 16:00	10/02/16 16:00	With Jetter Clean out 4 No Gullies and Clean / empty Soak-away Manhole (in garden). Last cleaned Sept/Oct '14.  Note - Attached plans & photos refer  - ***** █ TO BE ON-SITE TO RECORD WATER LEVELS IN SOAK-AWAY*****
R-48809	GULLY Cover broken	11/02/16 08:19	█	- Replace 1 No broken Newmill type Gullu Grating - 580 x 275mm (if required, use new re-cycled material grating, cut to size)  also  - Replace missing internal cover plate to stop silt enterring soak-away	Closed	11/02/16 08:21	Priority 2	09/03/16 16:00	23/02/16 16:00	- Replace 1 No broken Newmill type Gullu Grating - 580 x 275mm (if required, use new re-cycled material grating, cut to size)  also  - Replace missing internal cover plate to stop silt enterring soak-away
R-49135	DRAINAGE Blocked Culvert/Pipe	22/02/16 11:01	█ (between Rail and River Bridges)	As discussed on site, 22/2/16.  - Clean. Jet and CCTV Camera 450mm dia. soak-away drain. (work to be done by B and S Pipeline Solutions)  - Please advise █ when you are to be on site.	Closed	22/02/16 11:09	Priority 2	20/03/16 16:00	09/03/16 16:00	As discussed on site, 22/2/16.  - Clean. Jet and CCTV Camera 450mm dia. soak-away drain. (work to be done by B and S Pipeline Solutions)  - Please advise █ when you are to be on site.
R-49292	CARRIAGEWAY Carriageway Defects	25/02/16 10:37	near no75	E&C Patch	Closed	25/02/16 10:37	Priority 2	23/03/16 16:00	15/03/16 16:00	E&C Patch

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-50583	TRAFFIC Road Safety	13/04/16 11:04	Pluscarden Road, opposite Grove Care Home	[REDACTED]	No Further Action Required					?
R-51080	CARRIAGEWAY Carriageway Defects	25/04/16 11:01	at jcn with grant st	E&C Patch	Closed	25/04/16 11:01	Priority 2	22/05/16 16:00	14/05/16 16:00	E&C Patch
R-51512	CARRIAGEWAY Carriageway Defects	18/05/16 10:51	[REDACTED]	E&C Patch	Closed	18/05/16 10:51	Priority 2	14/06/16 16:00	13/06/16 16:00	E&C Patch
R-51777	CARRIAGEWAY Oil/Diesel On Road	24/05/16 08:55	Pluscarden Road , near Dr Grays Hospital	Oil or fuel spill	Closed	24/05/16 09:15	Emergency	24/05/16 11:15	24/05/16 09:35	Treat small oil spill on road on 24/5/16 at 09:15
R-52500	IRONWORK Cover broken	15/06/16 13:49	On footway at [REDACTED] Pluscarden Road	Scottish Water Buchan Trap cover is rusted through.  Report to Scottish Water via Symology.  - Damaged Buchan Trap Cover - CAT 3 Defect - Attached photos refer	Re-Directed to Third Parties					[REDACTED] attended. ?

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
(Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-53298	CARRIAGEWAY Carriageway Defects	14/07/16 10:56	[REDACTED] Plusgarden Road	[REDACTED]	Noted					?
R-55784	GULLY Blocked	08/11/16 16:42	Pluscarden Rd [REDACTED]	4 gullies along this stretch of road blocked with leaves	No Further Action Required					?
R-55785	GULLY Blocked	08/11/16 16:44	Junction of Wiseman Rd and Pluscarden Rd	Blocked gully	No Further Action Required					?
R-56771	CARRIAGEWAY Drainage Defects/Problems	10/01/17 12:31	[REDACTED] (between Railway and River Bridges)	Blocked drain causing flooding on the road [REDACTED]	Closed	11/01/17 08:00	Programmed Work	31/03/17 16:00	29/05/17 16:00	- Clean out 4 No Gullies (on Pluscarden Rd)  and  - Empty out Soak-away Chamber (in Garden) and clean out Sump if required. Note - Long hoses for Tanker are required for this.  (Note- R-54607 currently issued for Cyclic clean of this area)
R-57660	CARRIAGEWAY Carriageway Defects	21/02/17 13:56	at manhole near palmers cross	E&C Patch	Closed	22/02/17 08:00	Priority 2	21/03/17 16:00	20/03/17 16:00	E&C Patch
R-57845	CARRIAGEWAY Carriageway Defects	24/02/17 13:40	Pluscarden Rd [REDACTED]	e & c patching.	Closed	25/02/17 08:00	Priority 2	24/03/17 16:00	27/03/17 16:00	e & c patching at above locations.
R-58527	CARRIAGEWAY Carriageway Defects	22/03/17 13:53	at entrance to staff car park	E&C Patch	Closed	23/03/17 08:00	Priority 2	19/04/17 16:00	07/04/17 16:00	E&C Patch

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-58558	FOOTWAY Footway Defects	23/03/17 09:13	Corner of Pluscarden Rd and Wittet Dr	There is a hedge effectively reduces the usable width of the pavement by half.	Noted					?
R-59850	FOOTWAY Footways	11/05/17 09:33	Between [REDACTED] and Palmerscross bridge	Construct 40m of footway to match existing width (approx1.2m) with associated drainage	Closed	11/05/17 09:33	Programmed Work	31/03/18 16:00	13/07/17 16:00	Construct 40m of footway to match existing width (approx1.2m) with associated drainage
R-60050	CARRIAGEWAY Carriageway Defects	18/05/17 13:26	[REDACTED]	E&C Patch	Closed	19/05/17 08:00	Priority 2	15/06/17 16:00	16/06/17 16:00	E&C Patch
R-60407	CARRIAGEWAY Miscellaneous	07/06/17 10:53	Bridge at Pluscarden [REDACTED]	[REDACTED]	Re-Directed to Third Parties					?

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-61543	DRAINAGE Drainage Investigation	12/07/17 08:30	[REDACTED]	Drainage Investigation.  1/ Excavate trial hole at end of existing soak-away pipe to confirm the ground conditions and construction of soak-away. Soak-away is a 450mm dia Filter Pipe which is approximately 1.30m to crown of pipe. - Prior to digging the trial hole, empty water from catch-pit at opposite end of pipe (with Gully Tanker) so that drain rods (Cobra reel) can be used to trace end of pipe and location where to dig.  2/ With Gully Tanker supply water for infilling test hole at end of soak-away to check soak-away quality of ground.  Note - - [REDACTED] to be on site - Attached PU Plans refer. NOTE - location of private water mains !	Closed	12/07/17 08:49	Priority 3	07/01/18 16:00	23/01/18 16:00	Drainage Investigation.  1/ Excavate trial hole at end of existing soak-away pipe to confirm the ground conditions and construction of soak-away. Soak-away is a 450mm dia Filter Pipe which is approximately 1.30m to crown of pipe. - Prior to digging the trial hole, empty water from catch-pit at opposite end of pipe (with Gully Tanker) so that drain rods (Cobra reel) can be used to trace end of pipe and location where to dig.  2/ With Gully Tanker supply water for infilling test hole at end of soak-away to check soak-away quality of ground.  Note - - [REDACTED] to be on site - Attached PU Plans and Location Plan refer. NOTE - location of private water mains !
R-61647	CARRIAGEWAY Miscellaneous	17/07/17 12:09	Traffic lights beside the Grove nursing home Pluscarden Road Elgin	Passed to [REDACTED] CPB email attached. 15/07/17 19:00	Noted					?
R-61954	CARRIAGEWAY Mud/Gravel on Road	03/08/17 11:06	Wittet Drive roundabout leading to Pluscarden Road.	Debris, chips and cement on the road. [REDACTED]	No Further Action Required					?
R-65408	GULLY Blocked	05/01/18 11:19	At Grove Nursing Home	Call out on 24/12/17 at 08:55 to clear blocked gully.	Closed	24/12/17 08:55	Emergency	24/12/17 10:55	24/12/17 09:45	Call out on 24/12/17 at 08:55 to clear blocked gully.  [REDACTED]   [REDACTED]   [REDACTED]   [REDACTED] attended

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-66508	TRAFFIC SIGN Turned	12/02/18 13:53	Pluscarden Road, just before roundabout on Wittet Drive.	Roundabout sign has become twisted and out of place. Thanks	Closed	13/02/18 08:24	Priority 2	12/03/18 16:00	14/02/18 16:00	Realign sign and side bracket to correct position.
R-66687	CARRIAGEWAY Carriageway Defects	20/02/18 10:59	[REDACTED]	E&C Patch	Closed	20/02/18 10:59	Priority 2	19/03/18 16:00	15/03/18 16:00	E&C Patch
R-66689	CARRIAGEWAY Carriageway Defects	20/02/18 11:08	on mini rondabout	E&C Patch	Closed	20/02/18 11:08	Priority 1	22/02/18 16:00	21/02/18 16:00	E&C Patch
R-67565	CARRIAGEWAY Carriageway Defects	20/03/18 13:48	opposite forteath st	E&C Patch	Closed	21/03/18 08:00	Priority 2	17/04/18 16:00	02/04/18 16:00	E&C Patch
R-68361	CARRIAGEWAY Carriageway Defects	16/04/18 10:45	[REDACTED]	E&C Patch	Closed	16/04/18 10:45	Priority 2	13/05/18 16:00	25/04/18 16:00	E&C Patch
R-68362	CARRIAGEWAY Carriageway Defects	16/04/18 10:52	[REDACTED]	E&C Potholes	Closed	16/04/18 10:52	Priority 2	13/05/18 16:00	03/05/18 16:00	E&C Potholes
R-68363	CARRIAGEWAY Carriageway Defects	16/04/18 10:55	[REDACTED]	E&C Patch	Closed	16/04/18 10:55	Priority 2	13/05/18 16:00	25/04/18 16:00	E&C Patch
R-68649	CARRIAGEWAY Carriageway Defects	20/04/18 15:41	Pluscarden Road	[REDACTED]	No Further Action Required					?
R-69421	CARRIAGEWAY Carriageway Defects	22/05/18 14:14	[REDACTED]	E&C Potholes	Closed	23/05/18 08:00	Priority 2	19/06/18 16:00	13/06/18 16:00	E&C Potholes
R-69422	CARRIAGEWAY Carriageway Defects	22/05/18 14:16	at rear of dr grays	E&C Potholes	Closed	23/05/18 08:00	Priority 2	19/06/18 16:00	13/06/18 16:00	E&C Potholes



**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-69527	CARRIAGEWAY Carriageway Defects	29/05/18 14:31	At Wittet Drive round-about	E & C Patching to shallow joints - 4 No areas - 8m length (6m2) approx.  Note - - Attached photos gives location of patches - Try to keep excess chippings to a minimum and dust with quarry dust - Ensure 'loose chipping signs' are in place. - To be done outwith normal working hours when traffic is reduced. - Consider using 'Hot' Bitumen from Surface Dress Tanker.	'worn out' Closed	30/05/18 08:00	Priority 3	25/11/18 16:00	09/06/18 16:00	E & C Patching to shallow joints - 4 No areas - 8m length (6m2) approx.  Note - - Attached photos gives location of patches - Try to keep excess chippings to a minimum and dust with quarry dust - Ensure 'loose chipping signs' are in place. - To be done outwith normal working hours when traffic is reduced. - Consider using 'Hot' Bitumen from Surface Dress Tanker.
R-70780	CARRIAGEWAY Miscellaneous	23/07/18 15:38	[REDACTED]	The wall to the back of the residents of wittet drive and pluscarden road Third Parties is damaged. [REDACTED] [REDACTED] [REDACTED] it looks like the wall has been hit and is very unsteady. Could easily fall onto a passersby by. Can you arrange repair immediately. Thanks as per email thanks [REDACTED]	Re-Directed to					?
R-70866	GULLY Blocked	03/08/18 13:53	Between Fleurs Drive and Wiseman Road junctions (including gullies on junctions)	Blocked drain, water has not cleared after rain. Thanks [REDACTED]	Closed	07/08/18 08:00	Priority 2	03/09/18 16:00	21/08/18 16:00	Clean out 12 No gullies  (flooding here on 3/8/18)

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-70879	CARRIAGEWAY Drainage Defects/Problems	03/08/18 15:49	[REDACTED]	Please see email received at the cc today	Closed	08/08/18 08:45	Priority 3	03/02/19 16:00	14/12/18 16:00	Flooding of garden / drive at [REDACTED] is occurring during heavy rain  1/ [REDACTED] Replace existing newmill type gully with Type G1 Pot.  2/ Replace / raise K3 kerbs (4 No) across access to No 78 to leave at least 30mm upstand. Existing quadrant kerbs either side of access can remain.  Note - Reinstate c/w and f/w in HRA - Attached Photo and PU info refers

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
				[REDACTED]						
R-71186	CARRIAGEWAY Pothole	23/08/18 08:43	west bound carriageway	E & C pothole , 1 pothole	Closed	23/08/18 08:43	Priority 2	19/09/18 16:00	28/08/18 16:00	E & C pothole , 1 pothole
R-71187	CARRIAGEWAY Pothole	23/08/18 08:46	east bound carriageway near kerb line [REDACTED]	E & C pothole ,1 pothole	Closed	23/08/18 08:46	Priority 2	19/09/18 16:00	28/08/18 16:00	E & C pothole ,1 pothole
R-72119	CARRIAGEWAY Pothole	25/09/18 11:02	1 pothole ,on east bound carriageway on the railway bridge	E & C pothole	Closed	25/09/18 11:02	Priority 2	22/10/18 16:00	24/10/18 16:00	E & C pothole
R-73461	GULLY Blocked	29/11/18 15:24	Between railway bridge and road bridge.	Drains are not coping with the heavy rain	Noted					?
R-73778	CARRIAGEWAY Pothole	13/12/18 10:47	Pluscarden road at Wittet drive, in a track approx 10 metres before the solar bollard on the northbound side. 1 pothole	Pothole	Closed	13/12/18 10:47	Priority 2	09/01/19 16:00	21/12/18 16:00	Pothole

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-74330	CARRIAGEWAY Drainage Defects/Problems	21/01/19 15:50	[REDACTED]	Is there any proposals to improve the drainage at this location?	Noted					?
R-75612	CARRIAGEWAY Pothole	28/02/19 12:51	[REDACTED] before street light no 24. 1 pothole	just E&C Pothole	Closed	01/03/19 08:00	Priority 2	28/03/19 16:00	22/03/19 16:00	E&C Pothole
R-75712	CARRIAGEWAY Drainage Defects/Problems	07/03/19 11:43	[REDACTED]	[REDACTED]	Closed	09/03/19 08:00	Priority 2	05/04/19 16:00	13/03/19 16:00	Clean out 4 No Gullies (inspected on 8/3/19 and 2 No full of silt /leaves)  Flooding here on 7/3/19
R-75768	CARRIAGEWAY Pothole	11/03/19 12:14	From access into Housing Scheme (at Pluscarden Rd) to mini-round/about at top of Housing Scheme	E & C repairs to shallow potholes - 20m2 total approx.	Closed	13/03/19 08:28	Priority 2	09/04/19 16:00	30/04/19 16:00	E & C repairs to shallow potholes - 20m2 total approx.
R-76270	CARRIAGEWAY Miscellaneous	26/03/19 14:12	[REDACTED]	[REDACTED]	Noted					
R-76360	CARRIAGEWAY Pothole	27/03/19 13:12	[REDACTED] next to street light no 2, at the drop kerbs. 1 edge pothole	E&C edge Pothole	Closed	28/03/19 08:00	Priority 2	24/04/19 16:00	24/04/19 16:00	E&C edge Pothole
R-76361	CARRIAGEWAY Ironwork Defects	27/03/19 13:21	[REDACTED], just after street light no 8, eastbound side	Scottish gas toby has sunken in the carriageway . Apparatus is causing damage to the surrounding area. Cat 2	Re-Directed to Third Parties					Scottish gas toby has sunken in the carriageway . Apparatus is causing damage to the surrounding area. Cat 2

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
(Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-76362	CARRIAGEWAY Pothole	27/03/19 13:27	(1) [REDACTED] (2) At the junction with Fleurs drive. 1 pothole	E&C Potholes	Closed	28/03/19 08:00	Priority 2	24/04/19 16:00	24/04/19 16:00	E&C Potholes
R-76363	CARRIAGEWAY Pothole	27/03/19 13:34	[REDACTED] 1 pothole, eastbound side	E&C Pothole	Closed	28/03/19 08:00	Priority 2	24/04/19 16:00	24/04/19 16:00	E&C Pothole
R-77149	CARRIAGEWAY Carriageway Defects	23/04/19 09:06	[REDACTED] on Pluscarden road	Several potholes, thank you [REDACTED]	No Further Action Required					Several potholes, thank you [REDACTED]
R-77185	CARRIAGEWAY Pothole	24/04/19 11:49	Between streets light no 48 and no 49. 1 pothole at the gully	E&C Pothole	Cancelled					
R-77914	CARRIAGEWAY Pothole	23/05/19 14:33	[REDACTED] centre of the road. 1 pothole	E&C Pothole	Closed	24/05/19 08:00	Priority 2	20/06/19 16:00	18/06/19 16:00	E&C Pothole
R-77915	CARRIAGEWAY Pothole	23/05/19 14:35	[REDACTED] 2 potholes	E&C Potholes	Closed	24/05/19 08:00	Priority 2	20/06/19 16:00	18/06/19 16:00	E&C Potholes
R-77916	CARRIAGEWAY Pothole	23/05/19 14:40	Around the roundabout. (street light no 15). 6 potholes	E&C Potholes	Closed	24/05/19 08:00	Priority 2	20/06/19 16:00	18/06/19 16:00	E&C Potholes
R-77917	CARRIAGEWAY Ironwork Defects	23/05/19 14:44	[REDACTED]	Scottish Water toby lid is missing in the carriageway. Apparatus is defective. CAT 2	Re-Directed to Third Parties					Scottish Water toby lid is missing in the carriageway. Apparatus is defective. CAT 2
R-77918	CARRIAGEWAY Pothole	23/05/19 14:47	[REDACTED] centre of the road. 2 potholes	E&C Potholes	Closed	24/05/19 08:00	Priority 2	20/06/19 16:00	18/06/19 16:00	E&C Potholes
R-77919	CARRIAGEWAY Pothole	23/05/19 14:51	[REDACTED] centre of the road. 5 potholes	E&C Potholes	Closed	24/05/19 08:00	Priority 2	20/06/19 16:00	18/06/19 16:00	E&C Potholes
R-79149	FOOTWAY Kerb Defect	27/06/19 12:15	[REDACTED] just past the drive access, westbound side	1 Kerb requires re-setting	Closed	28/06/19 08:00	Priority 2	25/07/19 16:00	11/07/19 16:00	Kerb requires re-setting
R-79150	CARRIAGEWAY Pothole	27/06/19 12:27	[REDACTED] just before the road narrows sign, at the gully. 1 pothole	E&C Pothole	Closed	28/06/19 08:00	Priority 2	25/07/19 16:00	24/07/19 16:00	E&C Pothole
R-79151	CARRIAGEWAY Ironwork Defects	27/06/19 12:35	Between street light no's 46 and 47, on the westbound side of the carriageway.	Bt manhole has sunken in the surrounding area. Cat 2	Re-Directed to Third Parties					Bt manhole has sunken in the carriageway, causing damage to the surrounding area. Cat 2
R-80042	GULLY Blocked	08/08/19 15:59	[REDACTED] (between River & Rail bridges)	[REDACTED]	Closed	13/08/19 07:40	Priority 2	09/09/19 16:00	28/08/19 16:00	Clean out 4 No gullies
R-81172	FOOTWAY Pothole	12/09/19 12:11	[REDACTED] 1 pothole at the kerb edge.	E&C Pothole	Closed	13/09/19 08:00	Priority 2	10/10/19 16:00	16/09/19 16:00	(flooding here 6th - 9th Aug) E&C Pothole

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-81230	CARRIAGEWAY Miscellaneous	17/09/19 15:47	[REDACTED]	[REDACTED]	No Further Action Required					
R-82061	CARRIAGEWAY Pothole	21/10/19 13:42	On Pluscarden Road, at the white markings as you exit Grant St.	E&C Patch	Closed	22/10/19 08:00	Priority 2	18/11/19 16:00	08/11/19 16:00	E&C Patch
R-82062	CARRIAGEWAY Pothole	21/10/19 13:47	[REDACTED] between the two sections of footpath on Pluscarden Rd.	E&C Potholes	Closed	22/10/19 08:00	Priority 2	18/11/19 16:00	08/11/19 16:00	E&C Potholes
R-83059	FOOTWAY Footway Defects	29/11/19 11:07	On the footway, [REDACTED] at the kerb edge. Please fill the small track that goes around the bend with E&C, to get rid of the trip hazard. (Approx 4m) There is also a small patch on the opposite side.	E&C Patches	Closed	29/11/19 11:07	Priority 2	26/12/19 16:00	05/12/19 16:00	E&C Patches
R-84548	CARRIAGEWAY Pothole	23/01/20 15:36	[REDACTED] at the road crossing. 2 E&C patches	E&C patches	Closed	24/01/20 08:00	Priority 2	20/02/20 16:00	27/01/20 16:00	E&C patches
R-84549	CARRIAGEWAY Pothole	23/01/20 16:00	[REDACTED] 1 pothole	E&C pothole	Closed	24/01/20 08:00	Priority 2	20/02/20 16:00	27/01/20 16:00	E&C pothole
R-85604	CARRIAGEWAY Pothole	26/02/20 15:15	[REDACTED] centre of the carriageway. 1 E&C patch.	E&C patch	Closed	27/02/20 08:00	Priority 2	25/03/20 16:00	28/02/20 16:00	E&C patch
R-85606	CARRIAGEWAY Pothole	26/02/20 15:52	On the railway bridge, on the eastbound side of the carriageway. 1 pothole	E&C pothole	Closed	27/02/20 08:00	Priority 2	25/03/20 16:00	28/02/20 16:00	E&C pothole
R-85607	CARRIAGEWAY Pothole	26/02/20 15:54	[REDACTED] eastbound side of the carriageway. 1 pothole	E&C pothole	Closed	27/02/20 08:00	Priority 2	25/03/20 16:00	28/02/20 16:00	E&C pothole
R-86462	CARRIAGEWAY Pothole	23/03/20 10:39	Just before Pluscarden Place 1 pothole on eastbound side	E&C pothole	Closed	23/03/20 10:39	Priority 2	19/04/20 16:00	01/07/20 16:00	E&C pothole
R-86463	CARRIAGEWAY Pothole	23/03/20 10:41	At edge of old track beside Pluscarden road junction 1 pothole on northbound side	E&C pothole	Closed	23/03/20 10:41	Priority 2	19/04/20 16:00	01/07/20 16:00	E&C pothole

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-86658	TRAFFIC Road Safety	13/04/20 09:35	B9010 Elgin- Dallas-Forres road	[REDACTED]	No Further Action Required					
R-86669	FOOTWAY Pothole	13/04/20 10:21	30mtrs after roundabout for A96 , 1 footpath pothole on hospital side	E&C footpath pothole	Closed	13/04/20 10:21	Priority 2	10/05/20 16:00	02/07/20 16:00	E&C footpath pothole
R-86670	CARRIAGEWAY Pothole	13/04/20 10:22	Just before Pluscarden Place 1 pothole on eastbound side	E&C Pothole	Closed	13/04/20 10:22	Priority 2	10/05/20 16:00	02/07/20 16:00	E&C Pothole
R-86671	CARRIAGEWAY Pothole	13/04/20 10:25	At edge of old track on northbound side of roundabout 1 pothole	E&C Pothole	Closed	13/04/20 10:25	Priority 2	10/05/20 16:00	02/07/20 16:00	E&C Pothole
R-87260	CARRIAGEWAY Pothole	12/05/20 10:27	Beside Street Light No 1 , 2 potholes	E&C Potholes	Closed	12/05/20 10:27	Priority 2	08/06/20 16:00	07/07/20 16:00	E&C Potholes
R-87261	CARRIAGEWAY Pothole	12/05/20 10:29	At top of central road beside roundabout 5 potholes	E&C Potholes	Closed	12/05/20 10:29	Priority 2	08/06/20 16:00	07/07/20 16:00	E&C Potholes
R-87262	CARRIAGEWAY Pothole	12/05/20 10:31	[REDACTED] , 1 pothole	E&C Pothole	Closed	12/05/20 10:31	Priority 2	08/06/20 16:00	07/07/20 16:00	E&C Pothole
R-87263	CARRIAGEWAY Pothole	12/05/20 10:32	[REDACTED] , 1 pothole	E&C Pothole	Closed	12/05/20 10:32	Priority 2	08/06/20 16:00	07/07/20 16:00	E&C Pothole
R-87264	CARRIAGEWAY Pothole	12/05/20 10:33	[REDACTED] 1 pothole	E&C Pothole	Closed	12/05/20 10:33	Priority 2	08/06/20 16:00	03/07/20 16:00	E&C Pothole
R-88033	GULLY Blocked	15/06/20 11:18	[REDACTED]	All 4 drains between the Railway Bridge and Road Bridge on Pluscarden Road are blocked. Caller says there is also a [REDACTED] [REDACTED] [REDACTED] [REDACTED] s [REDACTED]	Closed	25/06/20 08:05	Priority 3	21/12/20 16:00	19/08/20 16:00	Clean out 4 No Gullies and 1 No Soak-away Catchpit (located in garden)  Note - Long suction hoses will be required for cleaning catchpit
R-88572	TRAFFIC SIGN Miscellaneous	27/07/20 14:56	Pluscarden Road	30 mph limit signs obscured by vegetation. [REDACTED]	Noted					
R-89152	CARRIAGEWAY Carriageway Defects	20/08/20 11:43	M a p l o c a t i o n : <a href="http://maps.google.com/?q=57.64543698857163,-3.328252046902569">http://maps.google.com/?q=57.64543698857163,-3.328252046902569</a>	pothole	No Further Action Required					?

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-89212	CARRIAGEWAY Pothole	24/08/20 09:46	Beside Grant street 1 centre line	E&C centre line pothole	Closed	24/08/20 09:46	Priority 2	20/09/20 16:00	31/08/20 16:00	E&C centre line pothole
R-89302	FOOTWAY Footway Defects	28/08/20 11:20	[REDACTED] Pluscarden Road	[REDACTED]	Closed	02/09/20 08:00	Priority 2	29/09/20 16:00	03/09/20 16:00	With Saw, cut (chamfer) to remove 'sharp corner' on kerbs - 2 No  (see attached photos)
R-89488	CARRIAGEWAY Debris on Road	07/09/20 14:26	At Wittet Drive junction (mini round-about)	Sweep up spilt concrete from road, 7/9/20 at 14:15  (Env Protection Sweeper attended)	Closed	07/09/20 14:15	Emergency	07/09/20 16:15	07/09/20 16:00	Sweep up spilt concrete from road, 7/9/20 at 14:15  (Env Protection Sweeper attended)
R-89744	CARRIAGEWAY Pothole	16/09/20 13:57	At the rounadbout, as you exit Pluscarden Road (Dallas side) onto Wittet Drive (as you head to the A96). 1 edge pothole	E&C edge pothole	Closed	17/09/20 08:00	Priority 2	14/10/20 16:00	22/09/20 16:00	E&C edge pothole
R-89745	CARRIAGEWAY Pothole	16/09/20 14:18	On Pluscarden Road, opposite Pluscarden Place, at the gully, on the eastbound side of the carriageway. 1 pothole	E&C pothole	Closed	17/09/20 08:00	Priority 2	14/10/20 16:00	22/09/20 16:00	E&C pothole
R-90044	GULLY Blocked	05/10/20 15:15	opposite the Grove Care Home	blocked gully, extensive flooding	No Further Action Required					



**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-90276	CARRIAGEWAY Miscellaneous	12/10/20 10:44	[REDACTED]	[REDACTED]	Noted					
R-90482	CARRIAGEWAY Drainage Defects/Problems	19/10/20 11:43	across from The Grove Care Home	[REDACTED]	Noted					

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-90637	CARRIAGEWAY Carriageway Defects	27/10/20 10:15	[REDACTED]	This is a re-occurring pot hole [REDACTED] [REDACTED] [REDACTED] [REDACTED] [REDACTED] [REDACTED] [REDACTED] [REDACTED] [REDACTED] [REDACTED]	Closed	29/10/20 08:00	Priority 2	25/11/20 16:00	03/11/20 16:00	With E & C, patch 'worn' / 'low' areas in old reinstatement patch - 2 m2 approx  Note - See attached photo - Noise / vibration issues being reported in house (No 72)
R-90670	CARRIAGEWAY Pothole	27/10/20 12:51	At the roundabout, on the northbound side of the carriageway, at the toby.	E&C pothole	Closed	28/10/20 08:00	Priority 2	24/11/20 16:00	30/10/20 16:00	E&C pothole
R-90671	CARRIAGEWAY Pothole	27/10/20 13:28	Opposite Street column no 1, on the eastbound side of the carriageway.	E&C edge patch at the gully	Closed	28/10/20 08:00	Priority 2	24/11/20 16:00	28/10/20 16:00	E&C edge patch at the gully
R-90941	GULLY Blocked	10/11/20 15:27	[REDACTED] Pluscarden Rd	Gully is choked with leaves and debris	No Further Action Required					
R-91165	CARRIAGEWAY Miscellaneous	13/11/20 15:09	Wall along pavement [REDACTED] [REDACTED] [REDACTED] [REDACTED] [REDACTED] nearest wittest drive roundabout	Called to report someone has hit this wall with car and drove off, Third Parties [REDACTED] [REDACTED] [REDACTED] [REDACTED] [REDACTED] s [REDACTED]	Re-Directed to Third Parties					
				Called to roads						

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-91275	CARRIAGEWAY Drainage Defects/Problems	18/11/20 13:39	Pluscarden Road	[REDACTED]	Noted					
R-91524	FOOTWAY Pothole	27/11/20 13:17	4m before Fleurs Rd, on the westbound footway. Please E&C the edge of the Bt box to get rid of the potential trip hazard plus a small patch on the lid	E&C Patch	Closed	28/11/20 08:00	Priority 2	25/12/20 16:00	15/12/20 16:00	E&C Patch
R-91525	CARRIAGEWAY Pothole	27/11/20 13:20	On Fleurs Rd, 10m from the junction. 1 pothole on the northbound side.	E&C Pothole	Closed	28/11/20 08:00	Priority 2	25/12/20 16:00	15/12/20 16:00	E&C Pothole
R-91526	FOOTWAY Pothole	27/11/20 13:34	[REDACTED] 1 patch at the kerb edge. 1 patch on the footway, (1m)	E&C Patches	Closed	28/11/20 08:00	Priority 2	25/12/20 16:00	11/12/20 16:00	E&C Patches

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-92018	CARRIAGEWAY Carriageway Defects	14/12/20 11:57	[REDACTED]	[REDACTED]	Noted					
R-92236	GULLY Blocked	22/12/20 09:18	Pluscarden Road	Email received 21/12 Gullies blocked on drains either side of Pluscarden Road [REDACTED]	Noted					
R-92358	WINTER MAINTENANCE Miscellaneous	07/01/21 07:54	Dr Grays Hospital, Elgin	30/12/2020 09:07hrs - Can you No Further arrange for 10 ton of grit to be delivered to Dr. Grays hospital please.  Purchase order will follow shortly.						
R-93279	GULLY Blocked	26/01/21 15:03	[REDACTED] (on north channel)	Fault Details Fault Area: Drain Ditch Fault Type: Blocked [REDACTED]	Closed	27/01/21 08:00	Priority 2	23/02/21 16:00	15/02/21 16:00	With Jetter clean out and jet outlet pipe of 1 No gully  (ponding / icing here, across footway and carriageway on 26/1/21)
R-93312	CARRIAGEWAY Pothole	26/01/21 10:06	East of Wiseman road	2 x E & C potholes	Closed	26/01/21 10:06	Priority 2	22/02/21 16:00	15/02/21 16:00	2 x E & C potholes

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-94155	WINTER MAINTENANCE Miscellaneous	16/02/21 13:46	Pluscarden Road	[REDACTED]	Noted					
R-94251	CARRIAGEWAY Pothole	17/02/21 08:20	60m west of Palmers cross entrance	E & C pothole	Closed	17/02/21 08:20	Priority 2	16/03/21 16:00	08/03/21 16:00	E & C pothole
R-95428	CARRIAGEWAY Pothole	11/03/21 09:09	60m east of palmers cross	E & C pothole	Closed	11/03/21 09:09	Priority 2	07/04/21 16:00	25/03/21 16:00	E & C pothole
R-95458	GULLY Blocked	15/03/21 08:11	At low point between River & Railway Bridges	Clean out 4 No gullies  (ponding here 14/3/21)	Completed	15/03/21 08:13	Priority 2	11/04/21 16:00	15/03/21 16:00	Clean out 4 No gullies  (ponding here 14/3/21)
R-97118	GULLY Blocked	05/05/21 11:50	[REDACTED]	Clean and JET blocked gully  (ponding here 5/5/21, jetting required)	Completed	05/05/21 11:52	Priority 2	01/06/21 16:00	06/05/21 16:00	Clean and JET blocked gully  (ponding here 5/5/21, jetting required)
R-98138	CARRIAGEWAY Pothole	19/05/21 16:07	[REDACTED] at the road crossing. 3 potholes	E&C potholes	Completed	20/05/21 08:00	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C potholes

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
(Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-98139	CARRIAGEWAY Pothole	19/05/21 16:14	On the railway bridge, 25m from street light no 46, eastbound side. 3 potholes	E&C potholes	Completed	20/05/21 08:00	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C potholes
R-98140	CARRIAGEWAY Pothole	19/05/21 16:16	At street light no 49, centre of the carriageway. 1 E&C patch	E&C Patch	Completed	20/05/21 08:00	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C Patch
R-98141	CARRIAGEWAY Pothole	19/05/21 16:22	5m from street light no 48, at the gully. 1 pothole	E&C edge pothole	Completed	20/05/21 08:00	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C edge pothole
R-98142	FOOTWAY Footway Defects	19/05/21 16:26	██████████ at the kerb edge. 2 E&C patches	E&C edge Patches	Completed	20/05/21 08:00	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C edge Patches
R-98157	CARRIAGEWAY Pothole	20/05/21 10:53	At the access to the cottages. 9 E&C Patches	Pluscarden E&C Patches	Completed	20/05/21 10:53	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C Patches
R-98158	CARRIAGEWAY Pothole	20/05/21 10:55	1) ██████████ pothole (2) ██████████ pothole (3) ██████████	1 E&C potholes 1 E&C potholes 1 E&C patch	Completed	20/05/21 10:55	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C potholes
R-98159	CARRIAGEWAY Pothole	20/05/21 11:01	1) ██████████ 9 E&C patches (2) At the other side of street light no 15. 1 pothole	E&C patches	Completed	20/05/21 11:01	Priority 2	16/06/21 16:00	21/06/21 16:00	E&C patches
R-98160	CARRIAGEWAY Pothole	20/05/21 11:05	██████████ 1 pothole	E&C pothole	Completed	20/05/21 11:05	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C pothole
R-98161	CARRIAGEWAY Pothole	20/05/21 11:07	██████████ 6 E&C patches	E&C patches	Completed	20/05/21 11:07	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C Patches
R-98162	CARRIAGEWAY Pothole	20/05/21 11:09	██████████ 2 potholes	E&C potholes	Completed	20/05/21 11:09	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C potholes
R-98163	CARRIAGEWAY Pothole	20/05/21 11:10	██████████ 2 potholes	E&C potholes	Completed	20/05/21 11:10	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C potholes
R-98164	CARRIAGEWAY Pothole	20/05/21 11:14	1) ██████████ potholes (2) ██████████ 4 potholes (3) ██████████ 2 potholes	E&C potholes	Completed	20/05/21 11:14	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C potholes
R-98165	CARRIAGEWAY Pothole	20/05/21 11:16	At street light no 16. 2 potholes	E&C potholes	Completed	20/05/21 11:16	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C potholes
R-98166	CARRIAGEWAY Pothole	20/05/21 11:20	On Pluscarden Rd, ██████████ potholes	E&C potholes	Completed	20/05/21 11:20	Priority 2	16/06/21 16:00	11/06/21 16:00	E&C potholes
R-99676	CARRIAGEWAY Pothole	23/06/21 13:39	Opposite street light no 42, at the manhole cover, wesbound side. 1 pothole	E&C pothole	Completed	24/06/21 08:00	Priority 2	21/07/21 16:00	14/07/21 16:00	E&C pothole

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
R-99683	DRAINAGE Drainage Improvement	24/06/21 13:55	[REDACTED]	2021/22 Capital Drainage improvement Scheme  Works to replace existing gully soakaway.  - Remove approximately 2/3 rds of existing 450mm dia soakaway pipe . Not remaining 1/3 rd of pipe and existing manhole to remain  - At end of remaining section of 450mm soakaway pipe, install 1050mm dia perforated manhole chamber with open base to act as soakaway chamber. Chamnber to have D400 frame & cover.  - Connect into this new chamber conecion of existing gully, 150mm dia.  - Replace the removed section of 450mm soakaway pipe with Polystorm Modular Soakaway Cells (or similar approved product), installed as per attached Sketch plan and cross / long Sections. Cells (0.4 x 0.5.1.0m) to be laid 2 No 'deep', over a length of approximately 12m x 2 to4m wide. Exact configuratuion of cells to be confirmed after location of existing water mains and ground conditions are confirmed.  - Connect new chamber and Polystorm cells together with 2 No 150mm fitler pipes.	Work Issued	25/06/21 08:00	Programmed Work	31/03/22 16:00	n/a	2021/22 Capital Drainage improvement Scheme  Works to replace existing gully soakaway -  1- Remove approximately 2/3 rds of existing 450mm dia soakaway pipe. Remaining 1/3 rd of pipe and existing manhole to remain.  2 - At end of remaining section of 450mm soakaway pipe, install 1050mm dia perforated manhole chamber, with open base, to act as soakaway chamber. Chamber to have D400 frame & cover.  3 - Connect into this new chamber, 'tail' from existing gully, 150mm dia.  4 - Replace the removed section of 450mm soakaway pipe with Polystorm Modular Soakaway Cells (www.ploypipe.com or similar approved product), installed as per attached Sketch plan and cross / long Sections. Cells (0.4 x 0.5 x 1.0m) to be laid 2 No 'deep', over a length of approximately 12m, at a width of 2 to 4m wide. Exact configuration / layout of cells, to be confirmed after location of existing private water mains and ground conditions are confirmed. Reinststate area above new soakaway in topsoil.  5 - Connect new chamber and

**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

**Enquiries / Defects Recorded**

Ref	Item Type / Detail	Enq. Date	Location Description	Enquiry Comments	Current Status	Issued Date	Defect Category	Target Date	Comp. Date	Job Comments
				<p>- On carriageway of Pluscarden Road, replace 2 No Newmill type gullies with Type G1 Pots.</p> <p>Note -            [REDACTED]</p> <p>- Attached Sketch layout plan, cross / long section plan, PU plans and Polystorm Technical details refer.            - Before excavations are to begin trial holes to be dug to confirm location of private water mains which run along southern boundary (near wall).</p>						<p>Polystorm cells together with 2 No 150mm filter pipes.</p> <p>6 - On carriageway of Pluscarden Road, replace 2 No Newmill type gullies with Type G1 Pots.</p> <p>Note -            [REDACTED]</p> <p>- Attached Sketch layout plan, cross / long section plans, PU plans and Polystorm Technical details refer.            - Before excavations are to begin trial holes are to be dug to confirm location of private water mains which run along southern boundary of plot (near wall).</p>
R-100728	FOOTWAY Footway Defects	13/08/21 13:56	Pluscarden Road	[REDACTED]	Noted					
R-101077	TRAFFIC SIGN Turned	24/08/21 09:49	Approach to Wittet Drive from the east	Mini roundabout sign turned	Completed	24/08/21 09:51	Priority 2	20/09/21 16:00	26/08/21 16:00	Re-align mini roundabout sign on side bracket.



**USRN Inspection / Defect Records**

**USRN** 26300631 - (USRN Start Date = 19/12/2018)  
**Street Name & Town** Pluscarden Road, Elgin  
**Filter Used** (Defect Or Inspection Date is greater than or equal to 01 January 2016 00:00:00) And  
 (Defect Or Inspection Date is less than or equal to 31 August 2021 00:00:00)

