

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023

Street :- 26,301,727 - B9022 from B9118 near Bridge of Isla to B9117 at Rothiemay

Inspection Defects

Safety Inspection Area E06 - 08 (Aug) on the 18th of August 2023

Survey Method: Driven (Rural) / Walked (Urban)

Defects: No Defects Recorded

Safety Inspection Area E06 - 09 (Sep) on the 20th of September 2023

Survey Method: Driven (Rural) / Walked (Urban)

Defects: Defect(s) Recorded



Instruction Reference: M-0133088

Instruction Created: 20/09/2023 13:45:00

Item Type: Carriageway

Item Detail: Pothole

Defect Category: P3 - 30 working days

Issued Date: 20/09/2023 13:45

Target Date: 01/11/2023 13:45

Completion Date: 03/10/2023 10:13

Current Status : Works Complete (Measure - Patching)

Location Description: On carriageway heading south on nrside wheeltrack

Made Safe Date: 01/01/9999 00:00:00

Description of Works: E&C 1 Pothole approx 300mm x 300mm x45mm



Instruction Reference: M-0133089

Instruction Created: 20/09/2023 13:47:00

Item Type: Carriageway

Item Detail: Pothole

Defect Category: P3 - 30 working days

Issued Date: 20/09/2023 13:47

Target Date: 01/11/2023 13:47

Completion Date: 03/10/2023 10:34

Current Status : Works Complete (Measure - Patching)

Location Description: On carriageway heading south on nrside wheeltrack

Made Safe Date: 01/01/9999 00:00:00

Description of Works: E&C 1 Pothole approx 350mm x 300mm x45mm

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023

Street :- 26,301,727 - B9022 from B9118 near Bridge of Isla to B9117 at Rothiemay

Inspection Defects

Safety Inspection Area E06 - 10 (Oct) on the 24th of October 2023

Survey Method: Driven (Rural) / Walked (Urban)

Defects: Defect(s) Recorded



Instruction Reference: M-0133822

Instruction Created: 24/10/2023 09:56:00

Item Type: Carriageway

Item Detail: Pothole

Defect Category: P3 - 30 working days

Issued Date: 24/10/2023 09:56

Target Date: 05/12/2023 09:56

Completion Date: 21/11/2023 09:33

Current Status : Works Complete (Measure - Patching)


Location Description: On carriageway heading south on nrside wheeltrack within 20mtrs of both

Made Safe Date: 01/01/9999 00:00:00

Description of Works: E&C 2 potholes approx

1x 300mm x300mm x45mm

1x 400mm x 350mm x 50mm



Instruction Reference: M-0133823

Instruction Created: 24/10/2023 10:03:00

Item Type: Carriageway

Item Detail: Pothole

Defect Category: P3 - 30 working days

Issued Date: 24/10/2023 10:03

Target Date: 05/12/2023 10:03

Completion Date: 21/11/2023 09:35

Current Status : Works Complete (Measure - Patching)

Location Description: On carriageway heading south on nrside wheeltrack

Made Safe Date: 01/01/9999 00:00:00

Description of Works: E&C 1Pothole / defect on old patch approx

Approx 600mm x 400mm x 40mm

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023


Street :- 26,301,727 - B9022 from B9118 near Bridge of Isla to B9117 at Rothiemay

Inspection Defects

Safety Inspection Area E06 - 10 (Oct) on the 25th of October 2023

Survey Method: *Driven (Rural) / Walked (Urban)*

Defects: *Defect(s) Recorded*



Instruction Reference: *M-0133873*

Instruction Created: *25/10/2023 07:37:00*

Item Type: *Drainage*

Item Detail: *Blocked Offlets*

Defect Category: *P3 - 30 working days*

Issued Date: *25/10/2023 07:37*

Target Date: *06/12/2023 07:37*

Completion Date: *24/11/2023 09:05*

Current Status : *Works Complete (Measure - A/C)*

Location Description: *Heading north From Loanhead croft to Sheilparks junction*

Made Safe Date: *01/01/9999 00:00:00*

Description of Works: *Clean blocked offlets both sides of road*