

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023

Street :- 26,352,936 - B9022 from B9117 at Rothiemay crossroads to C42H near Shielparks,

Enquiries Not Progressed



Enquiry Reference: E-60103

Enquiry Created: 28/09/2023 10:28:00

Item Type: Carriageway

Item Detail: Pothole

Location Description: Fault Location

Street: B9022

Town:

Location of fault: On B9022 around a quarter of a mile after the junction with B9117 heading east towards Cornhill

Comments: Fault Details

Fault Area: Road Surface

Fault Type: Pothole

Subcategory Fault Type:

Further Fault Details: Large pothole on the B9022 around a quarter of a mile passed the junction with the B9117. Travelling home from Huntly to Banff at 9.30pm, car hit a large pothole which couldn't be seen in the dark, tyre instantly started to lose pressure, damaged alloy wheel. Would like an insurance form to be emailed for the damages.

Enquiry Status : No Further Action



Enquiry Reference: E-60123

Enquiry Created: 03/10/2023 09:08:00

Item Type: Carriageway

Item Detail: Carriageway Defects

Location Description: B9022

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023

Street :- 26,352,936 - B9022 from B9117 at Rothiemay crossroads to C42H near Shielparks,

Enquiries Not Progressed

Comments: Please see email below and send out a claim form to property:
Good morning

I write to advise I was driving along the B9022 last night and hut a very large pothole at around 1945 hours.

I attach photos of my left front drivers alloy wheel which has been damaged as a result of the hole in the road.

I also went back out this morning to get photos of the pothole in question when it was daylight. I attach photographs which shows the extent of the hole with a measuring tape which also shows the length, depth and width of the hole.

I have today received a quote from Hawco Volkswagen for the replacement of a new alloy which I also attach. I will also require to get my wheels realigned.

I send you this email being a claim that I wish to pursue against Moray Council for reimbursement of the costs involved that this has caused me at no fault of my own. I look forward to hearing from you in early course.

Regards

[Redacted signature]

Enquiry Status : No Further Action

Enquiry Reference: E-60132

Enquiry Created: 04/10/2023 10:15:00

Item Type: Carriageway

Item Detail: Pothole

Location Description: Street: B9022

Town: Rothiemay

Location of fault: On the B9022 road heading to Glenbarry from Huntly, between the crossroads and Shielparks

Comments: Deep pothole on road

Enquiry Status : No Further Action



Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023

Street :- 26,352,936 - B9022 from B9117 at Rothiemay crossroads to C42H near Shielparks,

Enquiries Not Progressed

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023

Street :- 26,352,936 - B9022 from B9117 at Rothiemay crossroads to C42H near Shielparks,

Reactive Defects



Instruction Reference: M-0133325

Instruction Created: 05/10/2023 08:52:00

Item Type: Carriageway

Item Detail: Pothole

Defect Category: P3 - 30 working days

Issued Date: 05/10/2023 08:52

Target Date: 16/11/2023 08:52

Completion Date: 17/10/2023 10:11

Current Status : Works Complete (Measure - Patching)

Location Description: On carriageway heading east on nrside edge

Made Safe Date: 01/01/9999 00:00:00

Description of Works: E and C 1 pothole approx 300mm x 250mm x45mm

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023

Street :- 26,352,936 - B9022 from B9117 at Rothiemay crossroads to C42H near Shielparks,

Inspection Defects

Safety Inspection Area E06 - 08 (Aug) on the 18th of August 2023


Survey Method: *Driven (Rural) / Walked (Urban)*

Defects: *No Defects Recorded*

Safety Inspection Area E06 - 09 (Sep) on the 20th of September 2023

Survey Method: *Driven (Rural) / Walked (Urban)*

Defects: *Defect(s) Recorded*



Instruction Reference: *M-0133086*

Instruction Created: *20/09/2023 13:38:00*

Item Type: *Carriageway*

Item Detail: *Pothole*

Defect Category: *P3 - 30 working days*

Issued Date: *20/09/2023 13:38*

Target Date: *01/11/2023 13:38*

Completion Date: *03/10/2023 09:22*

Current Status : *Works Complete (Measure - Patching)*

Location Description: *On carriageway heading south on nrside wheeltrack*

Made Safe Date: *01/01/9999 00:00:00*

Description of Works: *E&C 1Pothole approx 350mm x 300mm x45mm*

Safety Inspection Area E06 - 10 (Oct) on the 24th of October 2023

Survey Method: *Driven (Rural) / Walked (Urban)*

Defects: *No Defects Recorded*