

Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023

Street :- 26,352,937 - B9022 from C42H near Shielparks to Aberdeenshire boundary at

Inspection Defects

Safety Inspection Area E06 - 08 (Aug) on the 18th of August 2023

Survey Method: *Driven (Rural) / Walked (Urban)*

Defects: *No Defects Recorded*

Safety Inspection Area E06 - 09 (Sep) on the 20th of September 2023

Survey Method: *Driven (Rural) / Walked (Urban)*

Defects: *No Defects Recorded*

Safety Inspection Area E06 - 10 (Oct) on the 24th of October 2023

Survey Method: *Driven (Rural) / Walked (Urban)*

Defects: *Defect(s) Recorded*



Instruction Reference: *M-0133824*

Instruction Created: *24/10/2023 10:20:00*

Item Type: *Carriageway*

Item Detail: *Pothole*

Defect Category: *P3 - 30 working days*

Issued Date: *24/10/2023 10:20*

Target Date: *05/12/2023 10:20*

Completion Date: *21/11/2023 10:43*

Current Status : *Works Complete (Measure - Patching)*

Location Description: *On carriageway heading north on nrside edge*

Made Safe Date: *01/01/9999 00:00:00*

Description of Works: *E&C 4 potholes approx*

2x 450mm x 350mm x 45mm

2x 300mm x300mm x40mm

Instruction Reference: *M-0133825*

Instruction Created: *24/10/2023 10:24:00*

Item Type: *Carriageway*

Item Detail: *Pothole*

Defect Category: *P3 - 30 working days*

Issued Date: *24/10/2023 10:24*

Target Date: *05/12/2023 10:24*

Completion Date: *24/11/2023 11:59*

Current Status : *Works Complete (Measure - Patching)*

Location Description: *On carriageway heading south on nrside wheeltrack*

Made Safe Date: *01/01/9999 00:00:00*



Moray Council

Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 31/07/2023 To 29/10/2023

Street :- 26,352,937 - B9022 from C42H near Shielparks to Aberdeenshire boundary at

Inspection Defects

Safety Inspection Area E06 - 10 (Oct) on the 24th of October 2023

Survey Method: *Driven (Rural) / Walked (Urban)*

Defects: *Defect(s) Recorded*

Description of Works: *E&C 1Pothole approx
1x 300mm x300mm x45mm*

Instruction Reference: *M-0133874*

Instruction Created: *25/10/2023 07:39:00*

Item Type: *Drainage*

Item Detail: *Blocked Offlets*

Defect Category: *P3 - 30 working days*

Issued Date: *25/10/2023 07:39*

Target Date: *06/12/2023 07:39*

Completion Date: *24/11/2023 13:33*

Current Status : *Works Complete (Measure - A/C)*

Location Description: *From Sheilparks junction to boundary at Ternemny*

Made Safe Date: *01/01/9999 00:00:00*

Description of Works: *Heading north Clean blocked offlets both sides of road*

