FOI Request - HGV Statistics - 101003518146

Human	Injury/Death YES/NO	Type of accident e.g T/P, REVERSING ETC	AEBS Fitted
Animal Struck YES/NO			
NO	NO	Caught A frame and broke switches on o/s	N
NO	NO	Caught plastic Cover on Concrete Bay	N
NO	NO	Reversed and caught plastic cover on door shutter	Ν
NO	NO	Reversed and hit rear supporting beam	Ν
NO	NO	TP vehicle collided with insured travelling in opposite direction	Ν
NO	NO	Hit in o/s/r by TP vehicle	Ν
NO	NO	Rear of vehicle caught frame	Ν
NO	NO	TP ran into O/S of insured	N
NO	NO	Door caught in wind twisted hinge	N
NO	NO	Reversed and hit verge	Ν
NO	NO	Reversed damaged spinner	N
NO	NO	Moving Lorry and hit ramp broke lens	Ν
NO	NO	Reversed and rear mudflap caught in excavation causing damage	N
NO	NO	Boom hit bridge causing damage	Ν
NO	NO	Lorry slid on ice hit tree damaged paddle	Ν
NO	NO	Hit TP mirror	Ν
NO	NO	Hit bank	Ν
NO	NO	Collided with Tree branch broke mirror	Ν
NO	NO	Reversed hit bank and cracked wing	Ν
NO	NO	Reversed hit skip	Ν
NO	NO	Driving out of shed rear hit steel beam damage to paddle	Ν
NO	NO	Reversed hit kerb	Ν
NO	NO	Hit mirrors with passing TP	Ν
NO	NO	TP Hit Trailer at Dump	Ν
NO	NO	Reversed hit shed	Ν
NO	NO	Driving off weighbridge wheel hit bollard	N
NO	NO	Pulled off weight bridge too quick and hit railings	Ν
NO	NO	Hit Parked Car	Ν
NO	NO	Hit by TP	Ν
NO	NO	Reversed & hit TP	Ν
NO	NO	Collided with Parked TP	Ν
NO	NO	Hit Gate	Ν
NO	NO	Clipped concrete bollard, hit rear	Ν
NO	NO	Not known	N
NO	NO	Metal Gate hit Van	N
NO	NO	Reversing hit kerb damaged mud flap	N
NO	NO	Unknown Damage	N

NO	NO	Tp Broke Mirror	Ν
NO	NO	Hit parked E048	Ν
NO	NO	Roller rolled onto back door of box	N
NO	NO	Unknown Damage	N
NO	NO	No damage, TP damage unknown	N
NO	NO	Hit fence breaking 2 slats	N
NO	NO	Reversed hit shed door	Y
NO	NO	Damaged pins on lorry	Ν
NO	NO	Reversed hit shed	N
NO	NO	Hit road surface when turning right	N
NO	NO	Caught Mirror on TP	N
NO	NO	Reversed hit grit bin	N
NO	NO	Reversed slipped hit bank	N
NO	NO	Reversed Hit School gate	N
NO	NO	Reversed hit bollard	N
NO	NO	Hit Ice landed in ditch	N
NO	NO	Reversed hit bollard	N
NO	NO	Mirror struck bus sign	N
NO	NO	Bent door in wind	N
NO	NO	Hit wall broke light	N
NO	NO	Reversed hit lamppost	N
NO	NO	Hit Tree broke windscreen	N
NO	NO	TP ran into back of lorry	N
NO	NO	Clipped TP wing mirror	N
NO	NO	TP Broke Mirrors	N
NO	NO	Reversing to tip damaged wing & m/flap	N
NO	NO	Alleged glass bottle fell from lorry damaging TP	N
NO	NO	Damage to TP wall	N
NO	NO	Hit branches of tree broke mirror	N
NO	NO	Hit tree branch damaged mirror	Ν
NO	NO	Slipped into Ditch	Ν
NO	NO	Collided with Tp at Junction	Ν
NO	NO	Hit Wall with rear of vehicle	N
NO	NO	Reversed hit barriers	Ν
NO	NO	Hit pole and wall to let TP pass	Ν
NO	NO	Hit by TP	Ν
NO	NO	Hit kerb damaged wing	Ν
NO	NO	Hit post damaged binlift	Ν
NO	NO	Swerved to avoid oncoming lorry landed in ditch	Ν
NO	NO	Clipped TP when letting them pass	Ν
NO	NO	TP tried to pass but struck insured	Ν
NO	NO	Struck Branch	Ν
NO	NO	Hit by E006	Ν
NO	NO	Reversed hit E017	Ν
NO	NO	Hit Gate	Ν

NO	NO	Hit by TP	Y
NO	NO	Hit parked car	Ν
NO	NO	Insured went to turn left out of junction and hit stationary TP parked car	Ν
NO	NO	TP lost control in black ice and drove into insured	Ν
NO	NO	Skidded on ice hit wall	Y
NO	NO	Reversed hit rock	Ν
NO	NO	Hit lamppost with rear	Ν
NO	NO	Damaged exhaust hit panier	Ν
NO	NO	Hit hanger door on entry	Ν
NO	NO	Hit wall whilst ploughing	Ν
NO	NO	Insured slid on snow and clipped back of TP	Ν
NO	NO	Slid on ice damaged snow plough	Ν
NO	NO	Damaged plough whilst ploughing, Plough not repairable	Ν
NO	NO	Reversed hit wall	Ν
NO	NO	Reversed into Garage hit beam	N
NO	NO	Hit parked Vehicle with back of lorry	Ν
NO	NO	Reversed road gave way and got stuck	N
NO	NO	Hit lamp post whilst turning in car park	Ν
NO	NO	Damage to water tank	Y
NO	NO	Reversed hit vegetation on top of fence and damaged mirror	N
NO	NO	Collided with Vehicle travelling opposite direction hit mirrors	Ν
NO	NO	Chips from vehicle damaged TP Windscreen	N
NO	NO	Hit Parked Car	N
NO	NO	Reversed hit shed damaged light	N
NO	NO	Mirror hit vehicle travelling opp direction	N
NO	NO	Boom came loose hit roads sign	Y
NO	NO	Damaged suction box on kerb	Ý
NO	NO	Tipped Body with tail gate closed	Ν
NO	NO	Unknown Damage to TP wall	N
NO	NO	Unknown Damage to TP wall	N
NO	NO	Unknown Damage to TP wall	Ν
NO	NO	Manoeuvrability tight on street. Driver travelling up the street and hit TP rear light	Ν
NO	NO	Swung round hit wall damaged casing	N
NO	NO	Unknown Damage to TP Vehicle	N
NO	NO	Driving down narrow road clipped TP wing mirror	N
NO	NO	Reversed hit blade damaged spinner	N
NO	NO	Reversed - hit TP	N
NO	NO	Reversed - hit bollard	N
NO	NO	Reversed - hit grass bank	N
NO	NO	Collided with TP at junction	N
NO	NO	Reverse manoeuvre lorry and hit lamppost	N
NO	NO	Hit Protruding iron works on road damaged brush	Y

NO	NO	TP ran into back of sweeper	Ν
NO	NO	Reversed hit side of TP artic lorry - Cleansing Paid	Ν
NO	NO	Knocked down traffic lights	Ν
NO	NO	Hit parked D056 when driving past	Ν
NO	NO	Hit lamppost when turning	Ν
NO	NO	Hit soft verge & tipped over into side	Y
NO	NO	Hit pole om weight bridge	Ν
NO	NO	Hit TP & Broke Mirror	Y
NO	NO	Broke LED Light	Y
NO	NO	Reversed hit container damaged door & Glass	N
NO	NO	Hit TP when turning out of junction	N
NO	NO	Digger hit Lorry	Y
NO	NO	Hit Loadall	Y
NO	NO	Reversed wing caught large mound	Y
NO	NO	Insured unaware of windscreen damage to TP car	N
NO	NO	Lorry rolled into 3 parked vehicles on High Street	N
NO	NO	Hit E159 with back of lorry	Y
NO	NO	Reversed hit TP parked Car	N
NO	NO	Reversed sunk in hold damaged mud guard	Y
NO	NO	Opened rear door & forgot to lift net	N
NO	NO	Easy Sheet damaged	Y
NO	NO	Caught rear lights on box when trying to load box on	N
NO	NO	Hit by branch broke windscreen	N
NO	NO	Door flew open hit other MC vehicle	Y
NO	NO	Bin lorry door hit D124	Ν
NO	Yes Injury	Slid on ice landed in ditch	Ν
NO	NO	Forgot to put back end down & hit door on way out of shed	Ν
NO	NO	Collided with Vehicle travelling opposite direction	Ν
NO	NO	Hit black ice slid hit fence	Ν
NO	NO	Hit parked van damaged mirrors	N
NO	NO	Reversed hit parked car	Y
NO	NO	Hit soft verge ended in ditch	Ν
NO	NO	Lorry slid in ice & hit wall & sign	N
NO	NO	TP travelling opposite direction hit plough managed mirror	Ν
NO	NO	Reversed hit wall	N
NO	NO	Damage to rear paddle	N
NO	NO	Reversed damaged binlift	Ν
NO	NO	Reversed lifted rear of lorry damaged light	N
NO	NO	Reversed digger damaged gate	Ν
NO	NO	Clipped Tp with rear of lorry	N
NO	NO	Turned and clipped wall	N
NO	NO	Scraped side of TP car (stopped)	N

NO	NO	TP hit by E073	Ν
NO	NO	Hit other vehicle whilst parking	Ν
NO	NO	Reversing - damaged rear paddle	Y
NO	NO	Unsure of collision with TP	Ν
NO	NO	Scraped bumper of TP parked car	Ν
NO	NO	Insured hit telephone pole	N
NO	NO	Hit stationary TP	Y
NO	NO	Hit bollards hanging from wall	N
NO	NO	TP hit insured in rear	Y
NO	NO	Damaged hopper - hit wall	N
NO	NO	Damaged hopper - hit fence	Y
NO	NO	Slid Ended in ditch	Y
NO	NO	E008 reversed hit E152	Y
NO	NO	Slid back hit embankment	Ν
NO	NO	Reversed Hit E152	Y
NO	NO	Slid on ice and hit wall	N
NO	NO	Hit stationary TP	N
NO	NO	Hit railing damaged lifter	Y
NO	NO	Slid on ice got stuck	Y
NO	NO	Damaged Rams	N
NO	NO	In ditch	N
NO	NO	Lorry ended in ditch	Y
NO	NO	Hit wall	Y
NO	NO	Reversed and hit wall	N
NO	NO	Reversed and hit lamppost	Y
NO	NO	Vehicles collided on narrow bridge - Mulben	N
NO	NO	Hit lamppost while reversing/manoeuvring	N
NO	NO	Reversed and hit bollard	N
NO	NO	Reversed and hit TP	N
NO	NO	Council vehicle clipped/broke mirror + s/window	Y
NO	NO	Caused damage to TP vehicle o/s	N
NO	NO	TP reversed and hit bollard	N
NO	NO	Passed E022 and damaged n/s mirror	N
NO	NO	Made contact with wall when tractor passed	Y
NO	NO	Vehicle in ditch damage when pulled out	N
NO	NO	Lower box struck workshop overhead door	N
NO	NO	TP mistook gap and damaged rear light cluster	N
NO	NO	Reversed into TP fence	Y
NO	NO	Caught edge of building when turning n/s/r	Y Y
NO	NO	Exhaust damaged & Side mirror caused by D088	Y Y
	NO	Door sprung open causing damage to hinge	
NO	NO		N
NO		Vehicle in ditch ice and snow covered road	N
NO	NO	Clipped barrier on bridge while gritting	N
NO	NO	TP claims chipped windscreen due to gritter	N
NO	NO	Caught pillar of bridge caused damage to computer	Ν

NO	NO	Scraped side of vehicle wall while driving	Ν
NO	NO	Hydraulic pipes & cables ripped off when disconnected	Ν
NO	NO	TP claims chipped windscreen/paintwork due to gritter	Ν
NO	NO	Landed in ditch n/s mud guard brackets broken	Ν
NO	NO	Our vehicle caused stone chips to front & side of van	Ν
NO	NO	Damaged TP wing mirror	Ν
NO	NO	TP Claims object fell off lorry and hit bonnet of car	Y
NO	NO	Clipped TP wing mirror when passing vehicle	Y
NO	NO	Scraped against bridge causing damage to bumper	Ν
NO	NO	HIT 3RD PARTY REAR WHILE MOVING FORWARD	Y
NO	NO	DROVE OVER 3RD PARTY SEPTIC TANK	Ν
NO	NO	DAMAGE TO H/LIGHT N/S INDICATOR - HIT BRANCH	Y
NO	NO	SLID ON MUD - DAMAGE TO FRONT N/S BUMPER	Y
		DRIVERS SIDE WINDSCREEN CRACKED SMALL	
NO	NO	STONE	Ν
NO	NO	HIT STATIONERY TP VEHICLE WHILE MANOEUVRING	Ν
NO	NO	COLLIDED WITH TP MIRROR WHEN PASSING	Ν
NO	NO	ROLLER DOORS DAMAGED	Y
NO	NO	DOOR SWUNG OPEN DAMAGED TP VAN	Y
NO	NO	HIT TP VEHICLE IN REAR - BUMPER DAMAGED	N
NO	NO	SCRAPED TP VEHICLE WHILE REVERSING	Y
NO	NO	TP CLAIM WE DAMAGE WING MIRROR	Ν
NO	NO	DAMAGE TP WALL WHILE REVERSING	Y
NO	NO	SCRATCHED VEHICLE ON WALL WHILE REVERSING	Y
NO	NO	TP SCRAPED VEHICLE WHILE PASSING - NO TP DETAILS	Y
NO	NO	TP COLLIDED WITH O/S MIRROR - NO TP DETAILS	N
NO	NO	TP DAMAGED WHEELS	Ν
NO	NO	SCRATCHED TP BUMPER N/S GOING AROUND CORNER	Y
NO	NO	HIT TP WING MIRROR / BROKEN	Y
NO	NO	DAMAGED BUMPER ON GRASS VERGE-VEHICLE PASSING	Y
NO	NO	TP OPENED DOOR WHILE PASSING DAMAGE TO DOOR	Y
NO	NO	INSURED REVERSED INTO PARKED TP VEHICLE	Y
NO	NO	HIT MIRROR AGAINST LAMP POST - REALIGN MIRRORS	Ŷ
NO	NO	HIT PARKED TP VEHICLE	Y
NO	NO	CAUGHT FENCE WHEN TURNING DAM TO EMER STOP/SCRAPE	Ŷ
NO	NO	SPLIT COVERING FOR EMER STOP BUTTON WHEN TURNING	Y

NO	NO	POSSIBLY SCRAPED PARKED TP VEHICLE	Y
NO	NO	WIND BLEW OPEN DOOR SMALL SCRATCH TO TP W/ARCH	Y
NO	NO	WHILE TURNING VEHICLE HIT BOLLARD	Y
NO	NO	E181 REAR HIT E027 MIRROR/GLASS WHILE PASSING	Y
NO	NO	T/P HIT INSURED	Y
NO	NO	INSURED HIT TP WING MIRROR	Ν
NO	NO	TURNING INTO JUNCTION SLID ON ICE HIT TREE	Y
NO	NO	LORRY SLID ON ICE INTO DITCH	Ν
NO	NO	LORRY SLID ON ICE HIT RAILING	Ν
NO	NO	REVERSED SLID HIT WALL	Y
NO	NO	REVERSED & HIT TP WALL	Y
NO	NO	INSURED SLID ON ICE HIT TP CAR	Y
NO	NO	REVERSED HIT T/P	Y
NO	NO	TP CROSSED LINE AND CLIPPED MIRROR	Y
NO	NO	REVERSED HIT SWEEPER WITH D157	Ν
NO	NO	PASSED TP AND MIRROR WAS HIT	Y
NO	NO	ENDED UP IN DITCH	Ν
NO	NO	T/P ATTEMPTED TO OVERTAKE AND ENDED UP ON TOP OF PLOUGH	Ν
NO	NO	SLID ON ICE INTO DITCH	Ν
NO	NO	HIT TP - DRIVERS SIDE	Y
NO	NO	NO DRIVER OWNING UP TO DAMAGE	Y
NO	NO	REVERSED & HIT TREE	Y
NO	NO	HIT GATE TURNING INTO A LAYBY	Y
NO	NO	MIRRORS CLIPPED PASSING ONCOMING TP - NO DAMAGE	Υ
NO	NO	HIT PARKED TP	Y
NO	NO	CLIPPED BANK WHILE TURNING - DAMAGE TO REAR PANEL	Y