

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

**Date Range:-** From 27/11/2024 To 27/11/2025

**Street :-** 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith

### Street Inspection History

Inspection Date	Survey Method	Defects
10/12/2024	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
20/01/2025	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
11/02/2025	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
11/03/2025	Driven (Rural) / Walked (Urban)	
10/04/2025	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
14/05/2025	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
20/06/2025	Driven (Rural) / Walked (Urban)	
09/07/2025	Driven (Rural) / Walked (Urban)	
19/08/2025	Driven (Rural) / Walked (Urban)	
10/09/2025	Driven (Rural) / Walked (Urban)	
21/10/2025	Driven (Rural) / Walked (Urban)	Defect(s) Recorded
18/11/2025	Driven (Rural) / Walked (Urban)	Defect(s) Recorded



**Instruction Reference:** M-0148134

**Instruction Created:** 10/12/2024 14:20:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 12 (Dec) on the 10th of December 2024

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 10/12/2024 14:20

**Target Date:** 28/01/2025 14:20

**Completion Date:** 13/12/2024 09:01

**Location Description:** On carriageway heading north on nrside wheeltrack

**Description of Works:** Cold Tar Pothole approx

1x 600mm x 300mm x 65mm ns wt

# Moray Council

## Inspection/Defect Report


This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0148135  
**Instruction Created:** 10/12/2024 14:25:00  
**Instruction Status :** *Works Complete*  
**Inspection:** Safety Inspection Area E05 - 12 (Dec) on the 10th of December 2024  
**Item Type:** Carriageway  
**Item Detail:** Pothole  
**Defect Category:** P2 - 5 Working Days  
**Issued Date:** 10/12/2024 14:25  
**Target Date:** 17/12/2024 14:25  
**Completion Date:** 12/12/2024 11:52  
**Location Description:** On carriageway heading north west on nrside wheeltrack  
**Description of Works:** Cold Tar Pothole approx 1x 1mtr x 650mm x 70mm ns wt



**Instruction Reference:** M-0148139  
**Instruction Created:** 10/12/2024 14:58:00  
**Instruction Status :** *Works Complete*  
**Inspection:** Safety Inspection Area E05 - 12 (Dec) on the 10th of December 2024  
**Item Type:** Carriageway  
**Item Detail:** Carriageway Defects  
**Defect Category:** P3 - 30 working days  
**Issued Date:** 10/12/2024 14:58  
**Target Date:** 28/01/2025 14:58  
**Completion Date:** 04/02/2025 13:28  
**Location Description:** On east bound carriageway edge as marked  
**Description of Works:** Hot tar Bowl fill approx 11mtrs x 500mm x 80mm+ ns edge



**Instruction Reference:** M-0148140  
**Instruction Created:** 10/12/2024 15:03:00  
**Instruction Status :** *Works Complete*  
**Inspection:** Safety Inspection Area E05 - 12 (Dec) on the 10th of December 2024  
**Item Type:** Verge  
**Item Detail:** Over-run damage  
**Defect Category:** P3 - 30 working days  
**Issued Date:** 10/12/2024 15:03  
**Target Date:** 28/01/2025 15:03  
**Completion Date:** 25/03/2025 08:05  
**Location Description:** From corner heading east to low point on carriageway

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Description of Works:** Using digger pull overrun verge back to road edge approx 100mtrs

**Enquiry Reference:** E-66420

**Enquiry Created:** 12/12/2024 15:12:00

**Enquiry Status :** *No Further Action*

**Item Type:** Carriageway

**Item Detail:** Carriageway Defects

**Location Description:** Diversion from Keith to Fochabers, I turned left onto the road and the pot hole was just as I turned onto the road, b9017 junction with a95

**Enquiry Comments:** email 12/12

**Fault Details**

**Fault Area:** Road Surface

**Fault Type:** Pothole

**Subcategory Fault Type:**

**Further Fault Details:** There was diversion in place at Keith and I was heading towards Fochabers so I turned right as diversion was shown followed road ahead to next diversion sign and turned left and the pot hole was more or less at the start of the road. I think the road could be the This happened at just after 6am on the 12-12-24 as soon as I did it low pressure came up on dash. Luckily I managed to drive the car home and took it to garage and the ture is damaged and needs a new tyre. The garage has still got the car at present and it needs a new tyre as far as I know. If poss ble i would I ke to claim the compensation. Regards [REDACTED]

**Enquiry Reference:** E-66764

**Enquiry Created:** 09/01/2025 15:55:00

**Enquiry Status :** *No Further Action*

**Item Type:** Carriageway

**Item Detail:** Carriageway Defects

**Location Description:** Pothole at what3words address ///dolly.operation.hats

**Enquiry Comments:** Incident occurred 12/12/2024 at just after 12am. Hitting the pothole lead to damage to tyre and immediate loss of tyre pressure. I was subsequently stranded from midnight until 8am in freezing temperatures until RAC could recover the vehicle. Replacement tyre cost £84. I would I ke a claim form issued to [REDACTED] please.



# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Enquiry Reference:** E-66913

**Enquiry Created:** 13/01/2025 14:09:00

**Enquiry Status :** *Completed*

**Item Type:** Drainage

**Item Detail:** Other Defect / Hazard

**Location Description:** customer called to report flooding on the road and also ditch damage on the 2 bends as you come into newmill from davoch side on the b9017

**Enquiry Comments:** customer called to report flooding on the road and also ditch damage on the 2 bends as you come into newmill from davoch side on the b9017

**Instruction Reference:** M-0148641

**Instruction Created:** 14/01/2025 10:33:00

**Instruction Status:** Works Complete

**Inspection:**

**Item Type:** Ditch

**Item Detail:** Blocked Ditch

**Defect Category:** P3 - 30 working days

**Issue Date:** 14/01/2025 10:33:00

**Target Date:** 25/02/2025 10:33:00

**Made Safe Date:** 01/01/9999 00:00:00

**Completion Date:** 25/03/2025 08:10:00

**Location Description:** customer called to report flooding on the road and also ditch damage on the 2 bends as you come into newmill from davoch side on the b9017

**Description of Works:** Using digger clear short sections of blocked ditch going uphill from corner



**Instruction Reference:** M-0148995

**Instruction Created:** 20/01/2025 15:13:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 01 (Jan) on the 20th of January 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 20/01/2025 15:13

**Target Date:** 03/03/2025 15:13

**Completion Date:** 20/02/2025 10:29

**Location Description:** On carriageway heading north on nrside wheeltrack

**Description of Works:** E&C Pothole approx  
1x 1mtr x 450mm x 45mm ns wt

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0148998

**Instruction Created:** 20/01/2025 15:14:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 01 (Jan) on the 20th of January 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 20/01/2025 15:14

**Target Date:** 03/03/2025 15:14


**Completion Date:** 20/02/2025 10:17

**Location Description:** On carriageway heading north westerly on offside wheeltrack

**Description of Works:** E&C 2 Potholes approx

1x 450mm x 350mm x 55mm os wt

1x 400mm x 350mm x 55mm ns wt



**Instruction Reference:** M-0148999

**Instruction Created:** 20/01/2025 15:17:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 01 (Jan) on the 20th of January 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 20/01/2025 15:17

**Target Date:** 03/03/2025 15:17

**Completion Date:** 20/02/2025 10:42

**Location Description:** On carriageway heading west on nrside wheeltrack

**Description of Works:** E&C 2 Potholes approx

1x 350mm x 300mm x 50mm ns wt

1x 300mm x300mm x 50mm ns wt


# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0149001

**Instruction Created:** 20/01/2025 15:20:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 01 (Jan) on the 20th of January 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 20/01/2025 15:20

**Target Date:** 03/03/2025 15:20

**Completion Date:** 04/02/2025 13:02

**Location Description:** On carriageway heading west on nrside at passing place

**Description of Works:** Hot tar Bowl fill approx 3edge phs approx

1x 900mmx 450mm x 75mm +

1x 1200mm x 450mmx 75mm +

1x 1500mm x 400mm x 75mm +

**Instruction Reference:** M-0149004

**Instruction Created:** 20/01/2025 15:28:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 01 (Jan) on the 20th of January 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 20/01/2025 15:28

**Target Date:** 03/03/2025 15:28

**Completion Date:** 04/02/2025 13:35

**Location Description:** On carriageway heading north on nrside wheeltrack

**Description of Works:** Hot 5ar Bowl fill approx

1x 2mtrs x 500mm x 75mm ns wt



# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0149008

**Instruction Created:** 20/01/2025 15:30:00

**Instruction Status :** Works Complete

**Inspection:** Safety Inspection Area E05 - 01 (Jan) on the 20th of January 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 20/01/2025 15:30

**Target Date:** 03/03/2025 15:30

**Completion Date:** 04/02/2025 13:41

**Location Description:** On carriageway heading north on west side of carriageway edge heading up to corner at top of hill

**Description of Works:** Hot tar Bowl fill approx 7 broken edge defects where water has washed away edge

Approx 1.5tons req

**Instruction Reference:** M-0149011

**Instruction Created:** 20/01/2025 15:36:00

**Instruction Status :** Works Complete

**Inspection:** Safety Inspection Area E05 - 01 (Jan) on the 20th of January 2025

**Item Type:** Verge

**Item Detail:** Erosion/Scour

**Defect Category:** P3 - 30 working days

**Issued Date:** 20/01/2025 15:36

**Target Date:** 03/03/2025 15:36

**Completion Date:** 28/03/2025 13:33

**Location Description:** From corner at top of hill heading up and round bend on south west side of carriageway

**Description of Works:** Replace section of washed out verge with recycled materials to protect road edge from further damage of erosion




# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0149020

**Instruction Created:** 20/01/2025 16:31:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 01 (Jan) on the 20th of January 2025

**Item Type:** Verge

**Item Detail:** Over-run damage

**Defect Category:** P3 - 30 working days


**Issued Date:** 20/01/2025 16:31

**Target Date:** 03/03/2025 16:31

**Completion Date:** 04/04/2025 07:17

**Location Description:** On south side of carriageway where veichle went off road opposite and beside passing place

**Description of Works:** Using digger pull back overrun verge to carriageway edge approx 100mtrs



**Instruction Reference:** M-0149021

**Instruction Created:** 20/01/2025 16:34:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 01 (Jan) on the 20th of January 2025

**Item Type:** Ditch

**Item Detail:** Blocked Ditch

**Defect Category:** P3 - 30 working days

**Issued Date:** 20/01/2025 16:34

**Target Date:** 03/03/2025 16:34

**Completion Date:** 04/04/2025 07:18

**Location Description:** On north side of carriageway next to passing place

**Description of Works:** Using digger clean and pull back overrun dich by veichle approx 80mtrs



**Enquiry Reference:** E-67338

**Enquiry Created:** 27/01/2025 11:56:00

**Enquiry Status :** *No Further Action*

**Item Type:** Grit Bin

**Item Detail:** Request for New / Install New

**Location Description:** Junction of B9017 and U51H near Newmill

**Enquiry Comments:** Customer requesting new grit bin at junction of B9017 and U51H near Newmill

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

**Date Range:-** From 27/11/2024 To 27/11/2025

**Street :-** 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0149322

**Instruction Created:** 28/01/2025 15:18:00

**Instruction Status :** *Works Complete*

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P2 - 5 Working Days

**Issued Date:** 28/01/2025 15:18

**Target Date:** 04/02/2025 15:18

**Completion Date:** 30/01/2025 10:54

**Location Description:** On carriageway heading west on ns and os wt

**Description of Works:** Hot tar Bowl fill 2 phs approx

1x 1.5mtrs x 1mtr x 70mm +ns wt

1x 500mm x 400mm x 70mm+os wt

**Instruction Reference:** M-0150091

**Instruction Created:** 11/02/2025 13:48:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 02 (Feb) on the 11th of February 2025

**Item Type:** Ditch

**Item Detail:** Blocked Ditch

**Defect Category:** P3 - 30 working days

**Issued Date:** 11/02/2025 13:48

**Target Date:** 25/03/2025 13:48

**Completion Date:** 01/04/2025 07:11

**Location Description:** Ditch heading away from roadside from culvert crossing

**Description of Works:** Using digger clear chocked ditch / outfall pipe side cast on to edge of bank and level off as req

Approx 50mtrs



# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0150106

**Instruction Created:** 11/02/2025 14:05:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 02 (Feb) on the 11th of February 2025

**Item Type:** Drainage

**Item Detail:** Blocked Culvert/Pipe

**Defect Category:** P3 - 30 working days


**Issued Date:** 11/02/2025 14:05

**Target Date:** 25/03/2025 14:05

**Completion Date:** 24/03/2025 15:39

**Location Description:** On south side of carriageway

**Description of Works:** Clear silt from chamber and jet both entrance and exit pipes within chamber



**Instruction Reference:** M-0150113

**Instruction Created:** 11/02/2025 14:12:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 02 (Feb) on the 11th of February 2025

**Item Type:** Drainage

**Item Detail:** Blocked Culvert/Pipe

**Defect Category:** P3 - 30 working days


**Issued Date:** 11/02/2025 14:12

**Target Date:** 25/03/2025 14:12

**Completion Date:** 24/03/2025 15:37

**Location Description:** On south side of carriageway nr gate of field

**Description of Works:** Using jetter clear any blockage from culvert pipe going into chamber



**Instruction Reference:** M-0150120

**Instruction Created:** 11/02/2025 14:16:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 02 (Feb) on the 11th of February 2025

**Item Type:** Ditch

**Item Detail:** Blocked Ditch

**Defect Category:** P3 - 30 working days

**Issued Date:** 11/02/2025 14:16

**Target Date:** 25/03/2025 14:16

**Completion Date:** 02/04/2025 07:12

**Location Description:** On north side of carriageway

**Description of Works:** Clear blocked and overrun ditch on north side of carriageway  
At culvert crossing

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0150126

**Instruction Created:** 11/02/2025 14:21:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 02 (Feb) on the 11th of February 2025

**Item Type:** Drainage

**Item Detail:** Blocked Culvert/Pipe

**Defect Category:** P3 - 30 working days


**Issued Date:** 11/02/2025 14:21

**Target Date:** 25/03/2025 14:21

**Completion Date:** 24/03/2025 15:37

**Location Description:** On north side of carriageway below passing place

**Description of Works:** Clear blocked culvert underneath passing place



**Instruction Reference:** M-0150128

**Instruction Created:** 11/02/2025 14:25:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 02 (Feb) on the 11th of February 2025

**Item Type:** Carriageway

**Item Detail:** Drainage Defects/Problems

**Defect Category:** P3 - 30 working days

**Issued Date:** 11/02/2025 14:25

**Target Date:** 25/03/2025 14:25

**Completion Date:** 08/04/2025 07:38

**Location Description:** On north side of carriageway at east end of passing place

**Description of Works:** Clean and pullback short section of badly overrun verge on east side of passing place approx 20mtrs



**Instruction Reference:** M-0151351

**Instruction Created:** 20/03/2025 10:59:07

**Instruction Status :** *Works Complete*

**Item Type:** Carriageway

**Item Detail:** Carriageway Defects

**Defect Category:** Programmed Work - End of Financial Year

**Issued Date:** 20/03/2025 11:08

**Target Date:** 01/01/9999 00:00

**Completion Date:** 08/04/2025 07:38

**Location Description:** Between Crossburn and U52H

**Description of Works:** Edge Strengthen 3no Passing Places

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0151984

**Instruction Created:** 10/04/2025 12:55:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 04 (Apr) on the 10th of April 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 10/04/2025 12:55

**Target Date:** 26/05/2025 12:55

**Completion Date:** 29/04/2025 10:18

**Location Description:** First 2 phs on carriageway one either side 3rd 4th 5th and 6th phs inside junction

**Description of Works:** E&C 6 Potholes approx

1x450mm x 300mm x 60mm ns wt

1x 250mm x 250mm x 45mm os wt

1x 1.5 mtrs x 1.5 mtrs x 45mm at junction

1x 400mm. 400mm x 50mm inside junction

1x 900mm x 900mm x 55mm inside junction

1x 500mm x 450mm x50mm inside junction

**Instruction Reference:** M-0151987

**Instruction Created:** 10/04/2025 13:03:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 04 (Apr) on the 10th of April 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 10/04/2025 13:03

**Target Date:** 26/05/2025 13:03

**Completion Date:** 29/04/2025 10:27

**Location Description:** On carriageway heading north on nrside wheeltrack

**Description of Works:** E&C Pothole approx

1x 300mm x 300mm x 45mm ns wt heading north



# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0151992

**Instruction Created:** 10/04/2025 13:11:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 04 (Apr) on the 10th of April 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 10/04/2025 13:11

**Target Date:** 26/05/2025 13:11

**Completion Date:** 29/04/2025 10:50

**Location Description:** On carriageway heading north on nrside wheeltrack

**Description of Works:** E&C 3 Potholes approx

1x 4mtrs x 300mm x 50mm ns edge

1x 500mm x 350mm x 50mm ns wt

1x 350mm x 350mm x 50mm ns wt



**Instruction Reference:** M-0153000

**Instruction Created:** 14/05/2025 11:51:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 05 (May) on the 14th of May 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 14/05/2025 11:51

**Target Date:** 25/06/2025 11:51

**Completion Date:** 22/05/2025 09:50

**Location Description:** On carriageway heading east on nrside edge

**Description of Works:** E&C Pothole approx

1x 900mm x 300mm x 50mm ns edge


# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Enquiry Reference:** E-69253

**Enquiry Created:** 10/09/2025 10:45:00

**Enquiry Status :** *Investigation (Follow Up)*

**Item Type:** Verge

**Item Detail:** Over-run damage

**Location Description:** On south side of carriageway opposite passing places along with other short sections between crossburn and A95

**Enquiry Comments:** Overrun sections mainly on the south side of carriageway, some soil is on edge of carriageway, mainly been caused by larger vehicles.



**Enquiry Reference:** E-69588

**Enquiry Created:** 21/10/2025 11:32:00


**Enquiry Status :** *No Further Action*

**Item Type:** Verge

**Item Detail:** Over-run damage

**Location Description:** On north side of carriageway heading east

**Enquiry Comments:** Overrun damage to verge which in turn has been pushed into ditch approx 35mtrs in length,  
Add to previous enquiry related to B9017



**Enquiry Reference:** E-69590

**Enquiry Created:** 21/10/2025 11:46:00

**Enquiry Status :** *No Further Action*

**Item Type:** Verge

**Item Detail:** Over-run damage

**Location Description:** On north side of carriageway 20mtrs east of

**Enquiry Comments:** Extensive overrun damage has been caused to verge causing ditch side to be pushed in approx 60mtrs in length  
Add to previous enquiry for B9017


# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Enquiry Reference:** E-69591

**Enquiry Created:** 21/10/2025 11:51:00

**Enquiry Status :** No Further Action


**Item Type:** Verge

**Item Detail:** Over-run damage

**Location Description:** On south side of carriageway

**Enquiry Comments:** Overrun damage has been caused to verge approx 50mtrs in length

Add to previous enquiry for B9017



**Enquiry Reference:** E-69592

**Enquiry Created:** 21/10/2025 11:56:00

**Enquiry Status :** No Further Action

**Item Type:** Ditch

**Item Detail:** Blocked Ditch

**Location Description:** On north side of carriageway

**Enquiry Comments:** Vehicle has entered and exited ditch partially blocking culvert

Add to previous raised enquiry for B9017



**Enquiry Reference:** E-69593

**Enquiry Created:** 21/10/2025 12:03:00

**Enquiry Status :** No Further Action

**Item Type:** Verge

**Item Detail:** Over-run damage

**Location Description:** On south side of carriageway

**Enquiry Comments:** Overrun damage caused to verge opposite passing place approx 60mtrs in length

Add to previous enquiry for B 9017


# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0156823

**Instruction Created:** 21/10/2025 12:07:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 10 (Oct) on the 21st of October 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days


**Issued Date:** 21/10/2025 12:07

**Target Date:** 02/12/2025 12:07

**Completion Date:** 31/10/2025 08:57

**Location Description:** On carriageway heading east on ns edge/wt at entry to passing place

**Description of Works:** E&C Pothole approx  
1x 400mm x 350mm x 60mm ns wt/edge



**Enquiry Reference:** E-69594

**Enquiry Created:** 21/10/2025 12:09:00

**Enquiry Status :** *No Further Action*

**Item Type:** Verge

**Item Detail:** Over-run damage

**Location Description:** On south side of carriageway

**Enquiry Comments:** Verge has excessive overrun from corner east of passing place heading west to west side of passing place  
Approx 150mtrs  
Add to previous enquiry for B 9017



**Enquiry Reference:** E-69595

**Enquiry Created:** 21/10/2025 12:12:00

**Enquiry Status :** *No Further Action*

**Item Type:** Ditch

**Item Detail:** Blocked Ditch

**Location Description:** On north side of carriageway

**Enquiry Comments:** Vehicle has entered and exited ditch pushing verge away from side of carriageway and partially blocking ditch approx 50mtrs

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

**Date Range:-** From 27/11/2024 To 27/11/2025

**Street :-** 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Enquiry Reference:** E-69596

**Enquiry Created:** 21/10/2025 12:28:00

**Enquiry Status :** *Instruction Issued*

**Item Type:** Verge

**Item Detail:** Over-run damage

**Location Description:** On south side of carriageway on corner

**Enquiry Comments:** Overrun damage to verge at corner approx 150mtrs in length

Add to previous enquiry for B9017

This is the last one, for this month

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

**Date Range:-** From 27/11/2024 To 27/11/2025

**Street :-** 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith

**Instruction Reference:** M-0158796

**Instruction Created:** 21/01/2026 11:29:45

**Instruction Status:** Works Issued

**Inspection:**

**Item Type:** Verge

**Item Detail:** Over-run damage

**Defect Category:** P3 - 30 working days

**Issue Date:** 10/02/2026 09:53:07

**Target Date:** 24/03/2026 09:53:07

**Made Safe Date:** 01/01/9999 00:00:00

**Completion Date:** 01/01/9999 00:00:00

**Location Description:** From junction with A95 west for 1130m to just short of junction with C72H.

**Description of Works:** As per attached Plan works can be marked as required, also if required on site contact [REDACTED] or [REDACTED] and we can be available.

From 6.5m on south side of carriageway pull back verge to gate at 125m

From 131m clean jet piped section on north side, and clear approx 5m of outfall from pipe, from same location clean ditch approx 50mtrs and pull back verge to passing place.

From 180m on south side of carriageway pull back verge to 330m.

From 218m on north side pull back verge to 235m at offset.

From 441m to 486m pull back verge on southside opposite passing place.

From 482m on both sides to overhead power cable crossing point pull back verges to 582m.

At 606m pull back verge on north side approx 14m to 620m at passing place, at 610m pull back verge on south side to 660m on west side of passing place.

From 660m to 803m pull back verge as req on both sides.

Clean 2 short sections of overrun ditch at either end before cross burn.

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Instruction Reference:** M-0157430

**Instruction Created:** 18/11/2025 11:54:00

**Instruction Status :** *Works Complete (Measure - Patching)*

**Inspection:** Safety Inspection Area E05 - 11 (Nov) on the 18th of November 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days


**Issued Date:** 18/11/2025 11:54

**Target Date:** 06/01/2026 11:54

**Completion Date:** 10/12/2025 13:30

**Location Description:** On carriageway heading west on ns wt

**Description of Works:** E&C Pothole a  
1x 300mm x 300mm x 45mm ns wt



**Instruction Reference:** M-0157431

**Instruction Created:** 18/11/2025 11:56:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 11 (Nov) on the 18th of November 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P2 - 5 Working Days


**Issued Date:** 18/11/2025 11:56

**Target Date:** 25/11/2025 11:56

**Completion Date:** 28/11/2025 10:29

**Location Description:** On carriageway heading west on ns edge /wt oppositeside to passing place

**Description of Works:** Compamac ph approx  
1x 600mm x 400mm x 70mm ns edge



**Instruction Reference:** M-0157432

**Instruction Created:** 18/11/2025 12:02:00

**Instruction Status :** *Works Complete*

**Inspection:** Safety Inspection Area E05 - 11 (Nov) on the 18th of November 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P2 - 5 Working Days

**Issued Date:** 18/11/2025 12:02

**Target Date:** 25/11/2025 12:02

**Completion Date:** 28/11/2025 10:28

# Moray Council

## Inspection/Defect Report

This report is produced from the the Council's HIAMS system and shows defects identified from inspections as well as defects and enquiries raised outside of inspections on the same Street during this period specified.

Date Range:- From 27/11/2024 To 27/11/2025

Street :- 26301306 - B9017 from Main Street in Newmill to A95 at Montgrew, Keith



**Location Description:** Both phs on carriageway ns wt heading east

1st ph on entry to to passing place

2nd ph on exit of passing place

**Description of Works:** Cold Tar 2 Potholes approx

1x 550mm x 400mm x 65mm ns edge

1x 650mm x 400mm x 70mm nscedge

**Instruction Reference:** M-0157433

**Instruction Created:** 18/11/2025 12:07:00

**Instruction Status :** Works Complete (Measure - Patching)

**Inspection:** Safety Inspection Area E05 - 11 (Nov) on the 18th of November 2025

**Item Type:** Carriageway

**Item Detail:** Pothole

**Defect Category:** P3 - 30 working days

**Issued Date:** 18/11/2025 12:07

**Target Date:** 06/01/2026 12:07

**Completion Date:** 12/12/2025 12:09

**Location Description:** On carriageway heading north on ns wt/edge

**Description of Works:** E&C Pothole a

1x 400mm x 400mmx 55mm ns wt

**Enquiry Reference:** E-69850

**Enquiry Created:** 20/11/2025 10:58:00

**Enquiry Status :** No Further Action

**Item Type:** Carriageway

**Item Detail:** Water Ponding

**Location Description:** A95 Near Chivas on the way to Banff.

**Enquiry Comments:** Call received 10:56 20/11/2025

A95 diversion near railway bridge is starting to flood.

