

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)  
**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 215273 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/03/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 214338 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/02/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 212819 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/01/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 212362 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/12/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 211248 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/11/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 210414 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/10/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 209545 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/09/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 208710 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 12/08/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 208298 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/07/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 207435 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 28/07/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 206813 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/06/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 206038 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/05/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 204912 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 31/03/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 204041 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/03/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 203235 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/02/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 202226 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/01/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 201502 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/12/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 200694 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/11/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 189829 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/09/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 188913 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/09/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 188047 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/08/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 187248 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/07/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 186408 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/06/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 186019 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/05/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 184849 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/04/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 183941 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/03/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 183351 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/02/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 182636 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/01/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 181710 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 07/12/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 180874 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/10/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 180481 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 11/10/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 179324 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/09/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 178916 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/08/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 177794 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 177027 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 176143 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 175481 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 172799 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 162667 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 158561 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 156790 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/12/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 152165 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/11/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 148482 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 145391 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 31/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 143400 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 142614 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/07/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 142372 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 13/06/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 141077 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/05/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 140371 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 139715 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 10/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 138884 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 138000 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 137261 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 17/11/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 136871 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 27/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21 Both seats replaced on 14.10.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 135917 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 28/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 134978 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/08/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 134506 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/07/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 133472 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 23/06/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 132709 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 17/05/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 131941 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 15/03/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 131163 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 16/02/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 130431 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 19/01/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Button seat chewed.01.21
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 129698 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 16/12/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 128882 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/08/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 128625 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 20/07/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 127608 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 12/06/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 127040 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 15/05/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 125953 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/03/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 125524 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/02/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 124419 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/01/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 123608 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/12/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 122932 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 11/11/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 122204 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/09/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 121430 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/09/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 120868 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/08/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 119832 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/07/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 119115 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/06/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 118561 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/04/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 117678 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/04/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 116894 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/03/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 116084 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 28/01/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 115437 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 07/01/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 115063 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 14/12/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 114427 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 09/11/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 113254 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/10/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 112503 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 24/09/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 111787 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/07/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 111069 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/07/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 110491 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/06/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 109603 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/04/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 108718 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/04/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 108141 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/03/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 107394 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 29/01/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 106506 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/11/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 106371 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/09/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 105099 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 24/07/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 104400 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 20/06/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 103732 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 09/03/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 102848 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/02/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Renew pipe chain covers
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 102169 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/01/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Renew pipe chain covers
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 101372 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/12/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	Renew pipe chain covers
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 101148 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 27/10/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 99932 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 22/08/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 99327 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 11/07/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 98495 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 13/06/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Cooper Park - Elgin (ELGICOOPAR)

**Area:** Elgin

**Plot Number:** 25.72

**Feature Id - Location:** Hurricane swing with two button seats (Wicksteed 6020 -069) o

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 98189 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/05/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 97387 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 16/03/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 96762 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/02/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Good	2.5000	

**Batch:** 95674 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 11/01/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	.0000	
Paintwork Condition	PAIN	Good	.0000	
Playground Equipment Stability	P001	Good	.0000	