

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2024 to 23/03/2026  
**Site:** Netherha Housing Scheme - Buckie (BUCKNEHOSC)  
**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Netherha Housing Scheme - Buckie (BUCKNEHOSC) **Area:** Buckie

**Plot Number:** 13.30 **Feature Id - Location:** Hurricane Swing  
**Feature Type:** Play Equipment Item **Contract Area:** Grounds Maintenance

**Batch:** 214653 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 02/03/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 213777 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 02/02/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 212917 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 05/01/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 212153 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 03/12/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 211420 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 04/11/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 210573 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 07/10/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Good	2.5000	
Paintwork Condition	PAIN	Good	2.5000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 209716 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 02/09/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2024 to 23/03/2026  
**Site:** Netherha Housing Scheme - Buckie (BUCKNEHOSC)  
**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Netherha Housing Scheme - Buckie (BUCKNEHOSC)

**Area:** Buckie

**Plot Number:** 13.30

**Feature Id - Location:** Hurricane Swing

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 209031 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 13/08/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 207822 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/06/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 207638 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 29/07/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 206955 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/06/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 205706 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/05/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 205076 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/04/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 204209 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/03/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2024 to 23/03/2026  
**Site:** Netherha Housing Scheme - Buckie (BUCKNEHOSC)  
**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Netherha Housing Scheme - Buckie (BUCKNEHOSC) **Area:** Buckie

**Plot Number:** 13.30 **Feature Id - Location:** Hurricane Swing  
**Feature Type:** Play Equipment Item **Contract Area:** Grounds Maintenance

**Batch:** 203400 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 04/02/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 202471 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 07/01/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 201689 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 03/12/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Excellent	.0000	Slight movement in bearing housing, reported previously 07 2024
Paintwork Condition	PAIN	Excellent	.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 200866 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 05/11/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 189967 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 01/10/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 189097 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 03/09/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 188226 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 06/08/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2024 to 23/03/2026  
**Site:** Netherha Housing Scheme - Buckie (BUCKNEHOSC)  
**Location Contains:** hurricane  
**Report Type:** Assessment

**Site:** Netherha Housing Scheme - Buckie (BUCKNEHOSC) **Area:** Buckie

**Plot Number:** 13.30 **Feature Id - Location:** Hurricane Swing  
**Feature Type:** Play Equipment Item **Contract Area:** Grounds Maintenance

**Batch:** 187399 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 02/07/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 186538 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 05/06/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 185668 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 30/04/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 185191 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 04/04/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 184403 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 07/03/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 183515 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 07/02/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 182801 - Inspection Batch

**Route:** Playground Inspection **Officer:** Playground Fitter **Date:** 09/01/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	