

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 215282 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/03/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 214300 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/02/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 212973 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/01/2026

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 212341 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/12/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 211191 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/11/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 210355 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/10/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 209497 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/09/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)  
**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 208978 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 13/08/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 208246 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/07/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 207460 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 28/07/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 206753 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/06/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 206018 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/05/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 204893 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 31/03/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 204001 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/03/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 203158 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/02/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 202292 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/01/2025

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Excellent	.0000	

**Batch:** 201445 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/12/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 200647 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/11/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 189807 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/09/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 188864 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/09/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 188015 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/08/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 187203 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/07/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 186361 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/06/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 185977 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/05/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 184797 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/04/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 183901 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/03/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 183313 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/02/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 182593 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/01/2024

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 181787 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 07/12/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	monitor seat condition.10/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 180821 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/10/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Dog chewing again, monitor seat condition.10Z/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 180426 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 11/10/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Dog chewing again, monitor seat condition.10Z/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 179282 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/09/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19.,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019 new seats fitted previously but have been badly dog chewed 5/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 178862 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/08/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19.,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019 new seats fitted previously but have been badly dog chewed 5/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 177726 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/07/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19.,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019 new seats fitted previously but have been badly dog chewed 5/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 176977 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/06/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19.,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019 new seats fitted previously but have been badly dog chewed 5/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 176167 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/05/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19.,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019 new seats fitted previously but have been badly dog chewed 5/23
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 175431 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/04/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19.,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 172757 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/03/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 162621 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/02/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 158518 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/01/2023

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 156647 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/12/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 152117 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/11/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 148424 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/10/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 145355 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 31/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 143382 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/08/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 142684 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/07/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 142322 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 13/06/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 141127 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/05/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 140320 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/04/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 139777 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 10/03/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 138847 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/02/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 138199 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 13/01/2022

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 137224 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 17/11/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 136717 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 27/10/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 135860 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 28/09/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 134927 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/08/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 134617 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/07/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 133415 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 23/06/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 132659 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 17/05/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 131895 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 15/03/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 131034 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 16/02/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)  
**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 130389 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 19/01/2021

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 129642 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 15/12/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 128911 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/08/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 128584 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 20/07/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 127558 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 12/06/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 127084 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 15/05/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 126010 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/03/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 125480 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/02/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 124396 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/01/2020

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 123580 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/12/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 122902 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 11/11/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 122155 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/09/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19,,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 121351 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 02/09/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Area around has been sprayed out again, 2.9.19. Chains seats piping fitted 6.8.19. Safa grass matting renewed 5.8.19.,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 120646 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/08/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Safa grass matting renewed 5.8.19.,Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 119891 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/07/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 119150 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/06/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required, chains and seats removed 4.6.2019
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 118543 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/04/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 117628 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/04/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 116881 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/03/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 116117 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 28/01/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 115385 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 07/01/2019

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 115017 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 13/12/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 114524 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 12/11/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing, new chains, piping, seats required
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)  
**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 113196 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 01/10/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 112699 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 26/09/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 111739 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/07/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 111011 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/07/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 110435 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/06/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 109552 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/04/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 108749 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 03/04/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 108084 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 06/03/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 107354 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 29/01/2018

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 106557 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 30/11/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 106310 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/09/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 105131 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 24/07/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 104334 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 20/06/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 103712 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 09/03/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)  
**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 102912 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/02/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 102236 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 05/01/2017

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 101423 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/12/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 101196 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 27/10/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 99996 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 22/08/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed, mats need need replacing
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 99266 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 11/07/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 98552 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 13/06/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Officer:** Playground Fitter (PLAY)  
**Route:** Playground Inspection (P011)  
**Inspected:** 01/01/2016 to 23/03/2026  
**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Location Contains:** maypole  
**Report Type:** Assessment

**Site:** Mayne Park and Road Verges - Elgin (ELGIMAPARO)

**Area:** Elgin

**Plot Number:** 7.80

**Feature Id - Location:** Maypole - Wicksteed

**Feature Type:** Play Equipment Item

**Contract Area:** Grounds Maintenance

**Batch:** 98246 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 04/05/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 97394 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 16/03/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 96815 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 08/02/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	5.0000	Grass safety matting sprayed out and mat exposed
Paintwork Condition	PAIN	Satisfactory	5.0000	
Playground Equipment Stability	P001	Satisfactory	5.0000	

**Batch:** 95689 - Inspection Batch

**Route:** Playground Inspection

**Officer:** Playground Fitter

**Date:** 11/01/2016

Observation Type	Code	Grade	Score	Notes
Overall Condition	G001	Satisfactory	.0000	Grass safety matting sprayed out and mat exposed
Paintwork Condition	PAIN	Satisfactory	.0000	
Playground Equipment Stability	P001	Satisfactory	.0000	